



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
053300	LOPRESTI BOOM BEAM INSPECTION	KMKE		MTH 11-Feb-2019 HRS 4167.1 LDG 3536		12 600		29-Feb-2020 4767.1	12 m 2 d 588.8
5-12-01 0512001	INSPECTION DOCUMENT 1 (INTERVAL 1A)	KMKE		MTH 28-Sep-2018 HRS 4003.4 LDG 3411		300		4303.4	125.1
5-12-02 0512002	INSPECTION DOCUMENT 2 (INTERVAL 1C)	KMKE		MTH 11-Feb-2019 HRS 4167.1 LDG 3536		12		29-Feb-2020	12 m 2 d
B262201 COCKPIT 0512016	WEIGHT CHECK PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 2 (INTERVAL 1C)	KMKE	A352TS X571976	MTH 24-Jan-2019		12		31-Jan-2020	11 m 4 d
5-12-04	INSPECTION DOCUMENT 4 (INTERVAL 3C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE		MTH 05-Nov-2013		36			
A323101 0512004 : GEAR	RESTORATION (HYDROSTATIC TEST) PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE : INSPECTION DOCUMENT 4 (INTERVAL 3C)	KMKE	40005320-2 1488	MTH 15-Mar-2017		36		31-Mar-2020	13 m 4 d
5-12-05	INSPECTION DOCUMENT 5 (INTERVAL 5C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE		MTH 22-Jul-2017 HRS 3335.1 LDG 2882 ACH 1124.8		60			
B262002 LEFT ENGINE 0512005 : L	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 5 (INTERVAL 5C)	KMKE	30401102-2 49122B1	MTH 20-Jul-2017		60		31-Jul-2022	41 m 4 d
B262002 RIGHT ENGINE 0512005 : R	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 5 (INTERVAL 5C)	KMKE	30401102-2 49121B1	MTH 20-Jul-2017		60		31-Jul-2022	41 m 4 d
5-12-06	INSPECTION DOCUMENT 6 (INTERVAL 6C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE		MTH 31-Mar-2016 HRS 2828.7 LDG 2433		72			
A262201 COCKPIT 0512006	SPECIAL DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 6 (INTERVAL 6C)	KMKE	A352TS X571976	MTH 29-Mar-2016		72		31-Mar-2022	37 m 4 d
5-12-07	INSPECTION DOCUMENT 7 (INTERVAL 12C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE		MTH 31-Mar-2016 HRS 2828.7 LDG 2433		144			
B262202 COCKPIT 0512007	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 7 (INTERVAL 12C)	KMKE	A352TS X571976	MTH 29-Mar-2016		144		31-Mar-2028	109 m 4 d
5-12-08 0512008	INSPECTION DOCUMENT 8 (INTERVAL 1A/2C)	KMKE		MTH 26-Aug-2018 HRS 3955.1 LDG 3358		24 300		31-Aug-2020 4255.1	18 m 4 d 76.8
5-12-09	INSPECTION DOCUMENT 9 (INTERVAL 2A/1C) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE		MTH 11-Feb-2019 HRS 4167.1 LDG 3536		4 200			
A243301	FUNCTIONAL CHECK BATTERY (CAPACITY CHECK) LEAD ACID BATTERY NOTE: THE INSPECTION INTERVAL CAN BE ADJUSTED AFTER THE USEFUL BATTERY LIFE IS ESTABLISHED BASED ON OPERATIONS TASK 24-33-00-720: INSPECTION DOCUMENT 9 (INTERVAL 2A/1C)	KMKE	RG-380E/44LA2 40919980	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		4 200		30-Jun-2019 4367.1	4 m 3 d 188.8
5-12-10 0512010	INSPECTION DOCUMENT 10 (INTERVAL 4A/3C)	KMKE		MTH 18-Mar-2017 HRS 3167 LDG 2753 ACH 1065.3		36 1200		31-Mar-2020 4367	13 m 4 d 188.7



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-11 0512011	INSPECTION DOCUMENT 11 (INTERVAL 8A/6C)	KMKE		MTH 18-Mar-2017 HRS 3167 LDG 2753 ACH 1065.3		36 1200		31-Mar-2020 4367	13 m 4 d 188.7
5-12-12 0512012	INSPECTION DOCUMENT 12 (14 CFR 91.207) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE		MTH 11-Feb-2019 HRS 4167.1 LDG 3536		12			
A256002	DETAILED INSPECTION ELT TRANSMITTER : INSPECTION DOCUMENT 12 (14 CFR 91.207)	KMKE	453-5000-999 170-05924	MTH 24-Jan-2019		12		31-Jan-2020	11 m 4 d
B256003	OPERATIONAL CHECK ELT TRANSMITTER EMERGENCY LOCATOR BEACON SYSTEM: INSPECTION DOCUMENT 12 (14 CFR 91.207)	KMKE	453-5000-999 170-05924	MTH 24-Jan-2019		12		31-Jan-2020	11 m 4 d
5-12-13	INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM) (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KMKE		MTH 11-Feb-2019 HRS 4167.1 LDG 3536		24			
341060 0512013 : RVSM	FUNCTIONAL CHECK RVSM SKIN WAVINESS: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE		MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
341066 LEFT 0512013 : L-ADC	CALIBRATION TEST AIR DATA DISPLAY UNIT FAR 91.411: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE	822-1109-004 J5PF	MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
341068 RIGHT 0512013 : R-ADC	CALIBRATION TEST AIR DATA DISPLAY UNIT FAR 91.411: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE	822-1109-004 HTRC	MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
341074 STANDBY 0512013 : STDBY	CALIBRATION TEST ALTIMETER/AIRSPEED INDICATOR FAR 91.411: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE	WL102AMS6 AP356	MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
B341001 LEFT 0512013 : L	FUNCTIONAL CHECK PITOT-STATIC SYSTEM: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE		MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
B341001 RIGHT 0512013 : R	FUNCTIONAL CHECK PITOT STATIC SYSTEM: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE		MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
B345001 NO. 1 0512013 : 1	CALIBRATION TEST TRANSPONDER NO. 1 TRANSPONDER FAR 91.413 (EXCEPT PHILLIPINES CERTIFIED AIRPLANES): INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE	89000067-002002 02873	MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
B345001 NO. 2 0512013 : 2	CALIBRATION TEST TRANSPONDER NO. 2 TRANSPONDER FAR 91.413 (EXCEPT PHILLIPINES CERTIFIED AIRPLANES): INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)	KMKE	89000067-002002 02875	MTH 09-Feb-2019		24		28-Feb-2021	24 m 1 d
5-12-14	INSPECTION DOCUMENT 14 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 02-May-2002		A/R			
A324103 LEFT MAIN GEAR 0512014C : L	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14	KMKE	3-1601-3 0238	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		T/C			
A324103 NOSE LANDING GEAR 0512014C : NOSE	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14	KMKE	3-1418 5466	MTH		T/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
A324103 RIGHT MAIN GEAR <i>0512014C : R</i>	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14	KMKE	3-1601-3 1374	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		T/C			
5-12-19	INSPECTION DOCUMENT 19			MTH 02-May-2002 HRS 0		5000		5000	821.7
5-12-21 <i>0512021</i>	INSPECTION DOCUMENT 21 (INTERVAL 2A/2C)	KMKE		MTH 07-Apr-2018 HRS 3728.5 LDG 3164		24 600		30-Apr-2020 4328.5	14 m 3 d 150.2
5-12-22 <i>0512022</i>	INSPECTION DOCUMENT 22 (NOT CURRENTLY USED)	*CF		MTH 02-May-2002		N/R			
5-12-23 <i>0512023</i>	INSPECTION DOCUMENT 23 (NOT CURRENTLY USED)	*CF		MTH 02-May-2002		N/R			
5-12-24 <i>0512024</i>	INSPECTION DOCUMENT 24 (INTERVAL 1A/1C)	KMKE		MTH 26-Aug-2018 HRS 3955.1 LDG 3358		12 300		31-Aug-2019 4255.1	6 m 4 d 76.8
5-12-25	INSPECTION DOCUMENT 25			MTH HRS		4000		5421.22	1242.92
5-12-26	INSPECTION DOCUMENT 26	KMKE		MTH 11-Feb-2019 HRS 4167.1 LDG 3536		6		31-Aug-2019	6 m 4 d
5-12-MA <i>05120MA</i>	INSPECTION DOCUMENT MA (CHAPTER 4)	KMKE		MTH 28-Sep-2018 HRS 4003.4 LDG 3411		300		4303.4	125.1
5-12-MC <i>05120MC</i>	INSPECTION DOCUMENT MC (CHAPTER 4)	KMKE		MTH 27-Dec-2017 HRS 3582.6 LDG 3077		1200		4782.6	604.3
5-12-MD <i>05120MD</i>	INSPECTION DOCUMENT MD (CHAPTER 4)	KMKE		MTH 31-Mar-2016 HRS 2828.7 LDG 2433		1425		4253.7	75.4
5-12-ME <i>05120ME</i>	INSPECTION DOCUMENT ME (CHAPTER 4)	*CF		MTH 02-May-2002 LDG 0		5000		5000	1454
5-12-MF <i>05120MF</i>	INSPECTION DOCUMENT MF (CHAPTER 4)	KMKE		MTH 23-Jul-2015 HRS 2546.6 LDG 2187		2550		5096.6	918.3
5-12-MG <i>05120MG</i>	INSPECTION DOCUMENT MG (CHAPTER 4)	KMKE		MTH 31-Jan-2016 HRS 2731.2 LDG 2344		2800		5531.2	1352.9
5-12-MH <i>05120MH</i>	INSPECTION DOCUMENT MH (CHAPTER 4)	KMKE		MTH 20-Nov-2016 HRS 3033.2 LDG 2624 ACH 1036.8		3100		6133.2	1954.9
5-12-MI <i>05120MI</i>	INSPECTION DOCUMENT MI (CHAPTER 4)	*CF		MTH 02-May-2002 HRS 0		4950		4950	771.7
5-12-MJ <i>05120MJ</i>	INSPECTION DOCUMENT MJ (CHAPTER 4)	*CF		MTH 02-May-2002 HRS 0		5000		5000	821.7
5-12-MK <i>05120MK</i>	INSPECTION DOCUMENT MK (CHAPTER 4)	*CF		MTH 02-May-2002 HRS 0		5050		5050	871.7
5-12-ML <i>05120ML</i>	INSPECTION DOCUMENT ML (CHAPTER 4)	*CF		MTH 02-May-2002 HRS 0		5050		5050	871.7



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-MM <i>05120MM</i>	INSPECTION DOCUMENT MM (CHAPTER 4)	*CF		MTH HRS	02-May-2002 0		6000		6000	1821.7
5-12-MP	INSPECTION DOCUMENT MP (CHAPTER 4)			MTH HRS	02-May-2002 0		8628		8628	4449.7
052001 E1	FJ44 CHECK 1	KMKE		MTH HRS LDG	14-Oct-2018 4022.4 3426		300		4322.4	144.1
052001 E2	FJ44 CHECK 1	KMKE		MTH HRS LDG	14-Oct-2018 4022.4 3426		300		4322.4	144.1
052002 E1	FJ44 CHECK 2	KMKE		MTH HRS LDG	07-Apr-2018 3728.5 3164		600		4328.5	150.2
052002 E2	FJ44 CHECK 2	KMKE		MTH HRS LDG	07-Apr-2018 3728.5 3164		600		4328.5	150.2
052003 E1	FJ44 CHECK 3	MKE		MTH HRS LDG	03-Apr-2014 1973.7 1704	.3	15000		16974	12795.7
052003 E2	FJ44 CHECK 3	MKE		MTH HRS LDG	03-Apr-2014 1973.7 1704	.1	15000		16973.8	12795.5
052004 E1	FJ44 CHECK 4			MTH HRS	02-May-2002 0	- 10526. 3	15000		4473.7	295.4
052004 E2	FJ44 CHECK 4			MTH HRS	02-May-2002 -10.2	- 10516. 1	15000		4473.7	295.4
052005 E1	FJ44 CHECK 5			MTH HRS	02-May-2002 0	-8026	15000		6974	2795.7
052005 E2	FJ44 CHECK 5			MTH HRS	02-May-2002 -10.2	-8016	15000		6973.8	2795.5
052006 E1	FJ44 CHECK 6			MTH HRS	02-May-2002 0	-5526	15000		9474	5295.7
052006 E2	FJ44 CHECK 6			MTH HRS	02-May-2002 -10.2	-5516	15000		9473.8	5295.5
052007 E1	FJ44 CHECK 7			MTH HRS	02-May-2002 0	-3026	15000		11974	7795.7
052007 E2	FJ44 CHECK 7			MTH HRS	02-May-2002 -10.2	-3016	15000		11973.8	7795.5
052008 E1	FJ44 CHECK 8			MTH HRS	02-May-2002 0	-526	15000		14474	10295.7
052008 E2	FJ44 CHECK 8			MTH HRS	02-May-2002 -10.2	-516	15000		14473.8	10295.5
052100	INSPECT INSPECTION ENVIROSYSTEMS 12 MO	KMKE		MTH HRS LDG	28-Sep-2018 4003.4 3411		12		30-Sep-2019	7 m 3 d
052101	INSPECTION ENVIROSYSTEMS 500 HR	KMKE		MTH HRS LDG ACH	11-Oct-2017 3437.9 2973 1168.4		500		1668.4	400.4
351005 <i>0512004 : OXY</i>	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER (DOT3HT1850 OR DOT3FC1850 OR ANY CYLINDER MANUFACTURED UNDER DOT-E-8162)- OXYGEN BOTTLE AND REGULATOR ASSEMBLY	KMKE		MTH HRS LDG	16-May-2015 2474.7 2119		60		31-May-2020	15 m 4 d



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
351006 PORTABLE	RESTORATION (HYDROSTATIC TEST) OXYGEN BOTTLE (DOT3AA)-OXYGEN BOTTLE AND REGULATOR ASSEMBLY		PN SN-UNKNOWN			N/R			
351007	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER OXYGEN BOTTLE (PART NUMBER 4444018-50 OR ANY CYLINDER MANUFACTURED UNDER DOT-E-10945 OR SP10945)-OXYGEN BOTTLE AND REGULATOR ASSEMBLY	KMKE	176274-50 673177801	MTH 16-May-2015 HRS 2474.7 LDG 2119		N/R			
542085 047103	INSPECT LEFT ENGINE FORWARD ENGINE MOUNT AFT CHANNEL WEB	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
542090 047103	INSPECT RIGHT ENGINE FORWARD ENGINE MOUNT AFT CHANNEL WEB	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
542095 047104	INSPECT LEFT ENGINE FORWARD ENGINE MOUNT FORWARD CHANNEL WEB	*CF		MTH 02-May-2002 HRS 0	12	12000		12012	7833.7
542100 047104	INSPECT RIGHT ENGINE FORWARD ENGINE MOUNT FORWARD CHANNEL WEB	*CF		MTH 02-May-2002 HRS 0	12	12000		12012	7833.7
542105 047107	INSPECT LEFT ENGINE AFT ENGINE MOUNT	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
542110 047107	INSPECT RIGHT ENGINE AFT ENGINE MOUNT	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
544005 047101	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AFT UPPER ANGLE COMMON TO AFT WEB, BL 34.90	*CF		MTH 02-May-2002 HRS 0		8628		8628	4449.7
544010 047101	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AFT UPPER ANGLE COMMON TO AFT WEB, BL 34.90	*CF		MTH 02-May-2002 HRS 0		8628		8628	4449.7
544015 047102	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AFT WEB UPPER EDGE, BL 26.56	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
544020 047102	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AFT WEB UPPER EDGE, BL 26.56	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
544035 047105	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
544040 047105	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
544045 047106	INSPECT LEFT ENGINE AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
544050 047106	INSPECT RIGHT ENGINE AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
551010 045501	INSPECT VERTICAL FIN FOR CRACKS AROUND FASTENERS,MAIN SPAR CAP AT UPPERMOST ATTACHMENT HOLE #1	*CF		MTH 02-May-2002 HRS 0	12	15000		15012	10833.7
551020 045502	INSPECT VERTICAL FIN FOR CRACKS AROUND FASTENERS,REAR SPAR CAP AT UPPERMOST ATTACHMENT HOLE #1	*CF		MTH 02-May-2002 HRS 0		11250		11250	7071.7
571010 045701	INSPECT LEFT WING FRONT SPAR , WS 88.50	*CF		MTH 02-May-2002 HRS 0		12000		12000	7821.7



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
<i>571015</i> <i>045701</i>	INSPECT RIGHT WING FRONT SPAR, WS 88.50 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571020</i> <i>045702</i>	INSPECT LEFT WING MAIN SPAR, WS 61.50 *CF		MTH HRS	02-May-2002 0		12500		12500	8321.7
<i>571025</i> <i>045702</i>	INSPECT RIGHT WING MAIN SPAR, WS 61.50 *CF		MTH HRS	02-May-2002 0		12500		12500	8321.7
<i>571030</i> <i>045703</i>	INSPECT LEFT WING MAIN SPAR, WS 102.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571035</i> <i>045703</i>	INSPECT RIGHT WING MAIN SPAR, WS 102.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571040</i> <i>045704</i>	INSPECT LEFT WING MAIN SPAR, WS 154.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571045</i> <i>045704</i>	INSPECT RIGHT WING MAIN SPAR, WS 154.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571050</i> <i>045705</i>	INSPECT LEFT WING MAIN SPAR, WS 171.00 (INBOARD) *CF		MTH HRS	02-May-2002 0		13000		13000	8821.7
<i>571055</i> <i>045705</i>	INSPECT RIGHT WING MAIN SPAR, WS 171.00 (INBOARD) *CF		MTH HRS	02-May-2002 0		13000		13000	8821.7
<i>571060</i> <i>045706</i>	INSPECT LEFT WING REAR SPAR, WS 136.65 *CF		MTH HRS	02-May-2002 0		13000		13000	8821.7
<i>571065</i> <i>045706</i>	INSPECT RIGHT WING REAR SPAR, WS 136.65 *CF		MTH HRS	02-May-2002 0		13000		13000	8821.7
<i>571070</i> <i>045707</i>	INSPECT LEFT WING REAR SPAR, WS 154.00 *CF		MTH HRS	02-May-2002 0		13000		13000	8821.7
<i>571075</i> <i>045707</i>	INSPECT RIGHT WING REAR SPAR, WS 154.00 *CF		MTH HRS	02-May-2002 0		13000		13000	8821.7
<i>571080</i> <i>045708</i>	INSPECT LEFT WING MAIN SPAR SPLICE, WS 111.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571085</i> <i>045708</i>	INSPECT RIGHT WING MAIN SPAR SPLICE, WS 111.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571090</i> <i>045709</i>	INSPECT LEFT WING REAR SPAR SPLICE, WS 111.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571095</i> <i>045709</i>	INSPECT RIGHT WING REAR SPAR SPLICE, WS 111.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571100</i> <i>045710</i>	INSPECT LEFT WING FRONT STRINGER SPLICE, WS 111.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7
<i>571105</i> <i>045710</i>	INSPECT RIGHT WING FRONT STRINGER SPLICE, WS 111.00 *CF		MTH HRS	02-May-2002 0		12000		12000	7821.7



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211001 LEFT	PRESSURE SHUTOFF VALVE	KMKE		5253-00-1 0755	MTH 19-Dec-2015 HRS 2686.3 LDG 2312 ACH 897.7		O/C	1 0		
211001 RIGHT	PRESSURE SHUTOFF VALVE	KMKE		5253-00-1 1278	MTH 20-Feb-2016 HRS 2775 LDG 2387		O/C			
211002 LEFT	VARIABLE VALVE	*CF		2601-21 0485	MTH 02-May-2002		O/C			
211002 RIGHT	VARIABLE VALVE	MKE		2601-21 0594	MTH 10-Aug-2011 HRS 1174.6 LDG 983		O/C	0 0		
211003	PRESSURE HEAT EXCHANGER	*CF		10840A 475	MTH 02-May-2002		O/C			
211005	EMERGENCY PRESSURE SHUTOFF VALVE	*CF		9912422-2 2601-23 0252	MTH 02-May-2002		O/C			
212001	BAGGAGE COMPARTMENT BLOWER	*CF		0113-12 0613	MTH 02-May-2002		O/C			
212003	(STO29) TEMPERATURE SWITCH	*CF		1173T42-1 3187	MTH 02-May-2002		O/C			
212302	WINDSHIELD AIR BLOWER MOTOR	*CF		7003-200 0818	MTH 02-May-2002		O/C			
213001	PRIMARY OUTFLOW VALVE	KMKE	A	52771-316 K653A	MTH 19-Jul-2013 HRS 1678.1 LDG 1427		O/C			
213002	SECONDARY OUTFLOW VALVE	*CF	A	9912409-15 866	MTH 02-May-2002		O/C			
213003	PRESSURE CONTROLLER	KMKE	E	52770-116 2116	MTH 15-Jun-2014 HRS 2069.7 LDG 1774		O/C	0 0 0		
213005	DIFFERENTIAL PRESSURE INDICATOR	*CF		C668511-0106 3001J73 22148	MTH 02-May-2002		O/C			
213008	MANUAL PRESSURE SWITCH	*CF	A	52773-001 1238	MTH 02-May-2002		O/C			
215000 AFT	EVAPORATOR BLOWER MOTOR	*CF		1250211-24 NSN	MTH 02-May-2002		O/C			
215000 FORWARD	EVAPORATOR BLOWER MOTOR	KMKE		1260185-1 2357	MTH 16-Mar-2015 HRS 2410.9 LDG 2067		O/C	0 0		
215001	FORWARD EVAPORATOR	*CF		1134300-3 175	MTH 02-May-2002		O/C			
215002	AFT EVAPORATOR	KMKE		1134820-15 943	MTH 09-May-2013 HRS 1629.5 LDG 1381		O/C	0 0 0		
215003	VAPOR CYCLE COMPRESSOR DRIVE MOTOR	SWF		1134146-1 857A	MTH 26-Jul-2007 ACH 241		O/C	0		
215004	COMPRESSOR DRIVE	*CF		1134610-1 187	MTH 02-May-2002		O/C			
215005	CONDENSOR ASSEMBLY	*CF		1134620-3 184	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215006	BINARY SWITCH	*CF		1250232-10 480	MTH 02-May-2002		O/C			
215007	RECEIVER DRYER ASSEMBLY 9912583-3	*CF		1134275-1 SN-UNKNOWN	MTH 02-May-2002		A/R			
215008	COMPRESSOR ASSEMBLY	*CF		1134635-1 127	MTH 02-May-2002		O/C			
215009	VANE AXIAL BLOWER ASSY KMKE			1250435-10 787	MTH 27-Apr-2018 HRS 3773.9 LDG 3195		O/C	0 0		
215010	AIR CONDITIONING FLIGHT HOURMETER *CF			1250703-3 SN-UNKNOWN	MTH 02-May-2002		O/C			
215011	COMPRESSOR DRIVE BELT *CF			225L100 SN-UNKNOWN	MTH 02-May-2002		O/C			
215012	VAPOR CYCLE COMPRESSOR DRIVE MOTOR BRUSHES MKE			1251171-6 NSN	MTH 13-Apr-2014 HRS 1973.7 LDG 1704 ACH 725.1			0 0 0 0	1525.1	257.1
216001	RAM AIR MODULATING VALVE MKE			27241287-24 7BC86	MTH 26-May-2013 HRS 1636.2 LDG 1391		O/C	0 0 0		
216002	TEMPERATURE CONTROLLER SWF			1E58-7 2BA18	MTH 25-May-2007 HRS 787		O/C	606		
216003 AFT	(TC007) SENSOR 9912085-3	*CF		27221274 11AU552	MTH 02-May-2002		O/C			
216003 FORWARD	(UT006) SENSOR 9912085-3	*CF		27221274 12AU626	MTH 02-May-2002		O/C			
221002 AILERON	SERVO MOUNT	*CF	1	622-5735-021 HX6F	MTH 02-May-2002		O/C			
221002 ELEVATOR	SERVO MOUNT	*CF		622-5735-022 HNPP	MTH 02-May-2002		O/C			
221002 RUDDER	SERVO MOUNT	KMKE		622-5735-022 12V3W	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		O/C			
221003 AILERON	SERVO SVO-3000	*CF		822-1168-002 HNKL	MTH 02-May-2002		O/C			
221003 ELEVATOR	SERVO SVO-3000	*CF		822-1168-001 HNLJ	MTH 02-May-2002		O/C			
221003 RUDDER	SERVO SVO-3000	KMKE		822-1168-001 1VK2	MTH 09-Jun-2017 HRS 3290.2 LDG 2838 ACH 1101.5		O/C	1 0		
221004	AUTOPILOT PANEL	KMKE	8	622-6208-223 2G9DT	MTH 11-Sep-2015 HRS 2591.6 LDG 2228 ACH 897.7		O/C	0 0		
231001	RECEIVER-EXCITER KTR0953	MKE		064-01015-0001 3504	MTH 25-Feb-2013 HRS 1580.7 LDG 1350		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
231002	POWER AMP/ANTENNA COUPLER KAC-952	MKE		064-01017-0001 13549	MTH 25-Feb-2013 HRS 1580.7 LDG 1350		O/C			
231003	MINIATURE-CONTROL ADAPTER KA-594	MKE		071-01268-0001 1249	MTH 25-Feb-2013 HRS 1580.7 LDG 1350		O/C	1076.7		
231005	MINATURE CONTROL KFS-594	GON		071-01274-0002 5142	MTH 30-Jun-2004 HRS 504		O/C	0		
231006 BOTTOM	VHF COMM 2 CONTROL KY-196B S3100-172	KMKE		064-01084-0201 3364	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		O/C			
231006 TOP	VHF COMM 1 CONTROL KY-196B S3100-172	KMKE		064-01084-0201 X0002316	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		O/C			
231007 BOTTOM	COMM 2 ANTENNA	*CF		17-40-02W 0435	MTH 02-May-2002		O/C			
231007 TOP	COMM 1 ANTENNA	MKE		18-50-01 1188	MTH 13-Apr-2014 HRS 1973.7 LDG 1704		O/C	0 0 0		
232003	TELEPHONE TRANSCEIVER *CF			900002-1 601123	MTH 02-May-2002		O/C			
232005	TELEPHONE ANTENNA *CF			CI5000 1041800	MTH 02-May-2002		O/C			
233005	UAT TRANSCEIVER	KMKE		89000016-150 1839P058	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0 0		
235001 LEFT	AUDIO AMPLIFIER S3100-63	KMKE	C	5636-1 0815	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		O/C			
235001 RIGHT	AUDIO AMPLIFIER S3100-63	KMKE	C	5636-1 1186	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		O/C			
237003	CVR MICROPHONE	*CF		S055-0065-00 161952	MTH 02-May-2002		O/C			
237004	CVR IMPACT SWITCH *CF			6895D2-X-5-5 3535	MTH 02-May-2002		O/C			
243001	BATTERY TEMP INDICATOR KUNU			3597-9 40003965	MTH 22-Mar-2013 HRS 1597.3 LDG 1360		O/C	0 0 0		
243003 LEFT	GENERATOR CONTROL UNIT *CF			51525-001F Y1887	MTH 02-May-2002		O/C			
243003 RIGHT	GENERATOR CONTROL UNIT *CF			51525-001F Y11042	MTH 02-May-2002		O/C			
243004	BATTERY TEMP MONITOR- *CF			1529-1-1 3649	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243006 LEFT	GENERATOR LOAD AMMETER *CF			C662501-0107 L21605	MTH 02-May-2002		O/C			
243006 RIGHT	GENERATOR LOAD AMMETER *CF			C662501-0107 K21615	MTH 02-May-2002		O/C			
243007	BATTERY S3597-4	KMKE		RG-380E/44LA2 40919980	MTH 07-Apr-2018 HRS 3728.5 LDG 3164		O/C	0 0		
243008	BATTERY RELAY *CF			A931F CM93404	MTH 02-May-2002		O/C			
243011	DC POWER VOLTMETER *CF			C662502-0101 A22148	MTH 02-May-2002		O/C			
245001 LEFT	START CONTROL P.C.B. *CF			6318324-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
245001 RIGHT	START CONTROL P.C.B. *CF			6318324-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
245002 LEFT	FUEL CONTROL P.C.B. *CF			6318341-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
245002 RIGHT	FUEL CONTROL P.C.B. *CF			6318341-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
245003 LEFT	IGNITOR CONTROL P.C.B. *CF			6318322-3 SN-UNKNOWN	MTH 02-May-2002		O/C			
245003 RIGHT	IGNITOR CONTROL P.C.B. *CF			6318322-3 SN-UNKNOWN	MTH 02-May-2002		O/C			
245004 LEFT	ANTI-ICE P.C.B. *CF			6318343-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
245004 RIGHT	ANTI-ICE P.C.B. *CF			6318343-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
245005 LEFT	PCB ATTENUATOR *CF			6318346-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245005 RIGHT	PCB ATTENUATOR *CF			6318346-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245006	ENVIRONMENTAL P.C.B. *CF			6318356-2 SN-UNKNOWN	MTH 02-May-2002		O/C			
245007	HYDRAULIC P.C.B. *CF			6318344-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245008	TRIM RELAY P.C.B. *CF			6518351-9 SN-UNKNOWN	MTH 02-May-2002		O/C			
245009	DIMMING P.C.B. *CF			6518353-4 SN-UNKNOWN	MTH 02-May-2002		O/C			
245010	GEAR LOGIC 1 P.C.B. *CF			6318345-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245011	FUEL FLOW PCB 9912417-3 *CF			85-230-2 0208002A	MTH 02-May-2002		O/C			
245012	SPEEDBRAKE P.C.B. *CF			6318347-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245013 LEFT	IDLE CONTROL P.C.B. *CF			6318348-11 SN-UNKNOWN	MTH 02-May-2002		O/C			
245013 RIGHT	IDLE CONTROL P.C.B. *CF			6318348-11 SN-UNKNOWN	MTH 02-May-2002		O/C			
245014	GEAR LOGIC 2 P.C.B. *CF			6318392-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245015	GEAR MONITOR P.C.B. *CF			6318394-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245016	TAIL DEICE P.C.B *CF			6318395-1 SN-UNKNOWN	MTH 02-May-2002		O/C			
245020	OVERVOLTAGE DETECTOR *CF			1645-1-3 2856	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
256000	ELT NAV INTERFACE UNIT MKE			453-6500 08599	MTH 22-Oct-2011 HRS 1208.5 LDG 1022		O/C	0 0 0		
256001	ELT TRANSMITTER C406-2	MKE		453-5000-999 170-05924	MTH 22-Oct-2011 HRS 1208.5 LDG 1022		O/C	0 0		
256002	ELT BEACON BATTERY PACK KMKE			452-0133 376679-021	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60		31-Jan-2023	47 m 4 d
Manufacture Date: 01-Jan-2018										
256004	ELT ANTENNA MKE			110-337 328036	MTH 22-Oct-2011 HRS 1208.5 LDG 1022		O/C	0 0		
256006 LAVATORY	LIFE VEST XF-35	KMKE		P01074-207 17071790292	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		O/C	6 0		
256006 NO. 1	LIFE VEST XF-35	KMKE		P01074-207 17071790413	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
256006 NO. 2	LIFE VEST XF-35	KMKE		P01074-207 17071790414	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
256006 NO. 3	LIFE VEST XF-35	KMKE		P01074-207 17071790217	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
256006 NO. 4	LIFE VEST XF-35	KMKE		P01074-207 17071790218	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
256006 NO. 5	LIFE VEST XF-35	KMKE		P01074-207 17071790219	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
256006 NO. 6	LIFE VEST XF-35	KMKE		P01074-207 17071790220	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
256006 NO. 7	LIFE VEST XF-35	KMKE		P01074-207 17071790221	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
256006 NO. 8	LIFE VEST XF-35	KMKE		P01074-207 17071790222	MTH 29-Jan-2018 HRS 3629.1 LDG 3106 ACH 1187.4		60	6	31-Jul-2022	41 m 4 d
261001 LEFT	FIRE DETECTOR SENSOR 9912416-1 *CF			3001-212-1004/455-9 204164	MTH 02-May-2002		O/C			
261001 RIGHT	FIRE DETECTOR SENSOR 9912416-1 *CF			3001-212-1004/455-9 204124	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
262001 LEFT ENGINE	FIRE EXTINGUISHER BOTTLE 9912048-6	SWF		30401102-2 49122B1	MTH 26-Jul-2007 HRS 815		O/C	0		
262001 RIGHT ENGINE	FIRE EXTINGUISHER BOTTLE 9912048-6	SWF		30401102-2 49121B1	MTH 26-Jul-2007 HRS 815		O/C	0		
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER HPN			A352TS X571976	MTH 07-Apr-2010 HRS 991 LDG 835		O/C	0 0 0		
262010 LEFT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE KMKE			13083-5 10012023	MTH 07-Apr-2018 HRS 3728.5 LDG 3164		72		30-Sep-2023	55 m 3 d
<i>262002 : L1</i> Manufacture Date: 30-Sep-2017										
262011 LEFT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE KMKE			13083-5 10012023	MTH 07-Apr-2018 HRS 3728.5 LDG 3164		72		30-Sep-2023	55 m 3 d
<i>262002 : L2</i> Manufacture Date: 30-Sep-2017										
262012 RIGHT ENGINE NO.1	FIRE EXTINGUISHER CARTRIDGE KMKE			13083-5 10012023	MTH 07-Apr-2018 HRS 3728.5 LDG 3164		72		30-Sep-2023	55 m 3 d
<i>262002 : R1</i> Manufacture Date: 30-Sep-2017										
262013 RIGHT ENGINE NO.2	FIRE EXTINGUISHER CARTRIDGE KMKE			13083-5 10012023	MTH 07-Apr-2018 HRS 3728.5 LDG 3164		72		31-Jan-2024	59 m 4 d
<i>262002 : R2</i> Manufacture Date: 04-Jan-2018										
272001	RUDDER BIAS VALVE KMKE			5307-1 1507C	MTH 16-Mar-2015 HRS 2410.9 LDG 2067		O/C	0 0		
273001	SHAKER CONTROL *CF A			201 5224	MTH 02-May-2002		O/C			
273002	ELEVATOR TRIM SERVO MKE			44430-3548 T1460	MTH 18-Jan-2012 HRS 1308.7 LDG 1095		O/C	0 0		
275001	SHUTOFF VALVE *CF			4083-1 210	MTH 02-May-2002		O/C			
275002 LEFT	FLAP ACTUATOR 9912365-5 *CF			1542000-7 1183	MTH 02-May-2002		O/C			
275002 RIGHT	FLAP ACTUATOR 9912365-5 *CF			1542000-7 1178	MTH 02-May-2002		O/C			
275004 RIGHT	FLAP ASSEMBLY KMKE			6325100-52 24129774	MTH 04-Aug-2014 HRS 2079 LDG 1780		O/C	0 0		
276001 LEFT	SPEED BRAKE ACTUATOR 9912375-4 *CF			1542100-5 1202	MTH 02-May-2002		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912375-4 *CF			1542100-5 1185	MTH 02-May-2002		O/C			
281001 LEFT	SURGE TANK FLOAT VALVE 9912016-2 *CF			35C10D 2318	MTH 02-May-2002		O/C			
281001 RIGHT	SURGE TANK FLOAT VALVE 9912016-2 *CF			35C10D 2297	MTH 02-May-2002		O/C			
282001 LEFT	FUEL BOOST PUMP 9912017-4 *CF			1C7-13 10AU162	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: CITATION PARTNERS, LLC
Aircraft Model: 525A - CJ2
Aircraft Serial: 525A-0071
Unit: 0071 Reg No: N701SF
Airworthiness: 02-May-2002
Print Date: 27-Feb-2019 11:37AM

Tracking Rate	Hours	Events/Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code	Description	City	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
282001	FUEL BOOST PUMP	*CF	1C7-13	MTH	02-May-2002				
RIGHT	9912017-4		8AU141			O/C			
282002	EJECTOR FUEL AFT PUMP		RG45310	MTH	02-May-2002				
LEFT	9912190-2	*CF	B8444			O/C			
282002	EJECTOR FUEL AFT PUMP		RG45310	MTH	02-May-2002				
RIGHT	9912190-2	*CF	B8481			O/C			
282003	SOLENOID VALVE	*CF	527700-103	MTH	02-May-2002				
LEFT	9914470-3		0141			O/C			
282003	SOLENOID VALVE	*CF	527700-103	MTH	02-May-2002				
RIGHT	9914470-3		0142			O/C			
282004	FUEL MOTOR VALVE		EM9014-3	MTH	02-May-2002				
LEFT	9912014-3	*CF	1180			O/C			
282004	FUEL MOTOR VALVE		EM9014-3	MTH	02-May-2002				
RIGHT	9912014-3	*CF	1181			O/C			
282005	EJECTOR FUEL FORWARD PUMP		RG45310	MTH	02-May-2002				
LEFT	9912190-2	*CF	B8495			O/C			
282005	EJECTOR FUEL FORWARD PUMP		RG45310	MTH	02-May-2002				
RIGHT	9912190-2	*CF	B8464			O/C			
282006	TRANSFER VALVE	*CF	ZSV57	MTH	02-May-2002				
	9914103-6		1092776			O/C			
284001	#5 FUEL PROBE	*CF	10664T05Y00	MTH	02-May-2002				
LEFT	9912589-5		0640			O/C			
284001	#5 FUEL PROBE	*CF	10664T05Y00	MTH	02-May-2002				
RIGHT	9912589-5		0646			O/C			
284002	#6 FUEL PROBE	*CF	10664T06Y00	MTH	02-May-2002				
LEFT	9912589-6		0681			O/C			
284002	#6 FUEL PROBE	*CF	10664T06Y00	MTH	02-May-2002				
RIGHT	9912589-6		0682			O/C			
284003	FUEL QUANTITY SIGNAL CONDITIONER	*CF	10663B01Y02	MTH	02-May-2002				
	9912589-9		01110581			O/C			
284004	#3 FUEL PROBE	*CF	10664T03Y00	MTH	02-May-2002				
LEFT	9912589-3		0648			O/C			
284004	#3 FUEL PROBE	*CF	10664T03Y00	MTH	02-May-2002				
RIGHT	9912589-3		0642			O/C			
284005	#4 INBOARD FUEL PROBE		10664T04Y00	MTH	02-May-2002				
LEFT	9912589-4	*CF	0831			O/C			
284005	#4 INBOARD FUEL PROBE		10664T04Y00	MTH	02-May-2002				
RIGHT	9912589-4	*CF	0821			O/C			
284006	#2 FUEL PROBE	*CF	10664T02Y00	MTH	02-May-2002				
LEFT	9912589-2		0655			O/C			
284006	#2 FUEL PROBE	*CF	10664T02Y00	MTH	02-May-2002				
RIGHT	9912589-2		0656			O/C			
284007	#1 FUEL PROBE	*CF	10664T01Y00	MTH	02-May-2002				
LEFT	9912589-1		0648			O/C			
284007	#1 FUEL PROBE	*CF	10664T01Y00	MTH	02-May-2002				
RIGHT	9912589-1		0647			O/C			
284008	FUEL LOW LEVEL SWITCH	*CF	L16H-9	MTH	03-Oct-2002				
LEFT			SN-UNKNOWN			O/C			
284008	FUEL LOW LEVEL SWITCH	*CF	L16H-9	MTH	03-Oct-2002				
RIGHT			SN-UNKNOWN			O/C			
284009	#4 OUTBOARD FUEL PROBE		10664T04Y00	MTH	02-May-2002				
LEFT	9912589-4	*CF	0832			O/C			
284009	#4 OUTBOARD FUEL PROBE		10664T04Y00	MTH	02-May-2002				
RIGHT	9912589-4	*CF	0825			O/C			
291002	HYDRAULIC PUMP	*CF	24195-LAC	MTH	02-May-2002				
LEFT	9912062-6		155			O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
291002 RIGHT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 160	MTH 02-May-2002		O/C			
291006	LOADING VALVE 9912423-39	*CF		4134-4 259	MTH 02-May-2002		O/C			
291007	PRESSURE SWITCH GAUGE KMKE			9912373-6 1426731	MTH 14-Dec-2016 HRS 3098.9 LDG 2687		O/C	0 0		
291008	HYDRAULIC MANIFOLD ASSY 9912423-40	*CF		8184-12 569	MTH 02-May-2002		O/C			
291009	RELIEF VALVE 9912423-38	*CF		2576-1 184	MTH 02-May-2002		O/C			
291010 LEFT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 U00485	MTH 02-May-2002		O/C			
291010 RIGHT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 U15785	MTH 02-May-2002		O/C			
291011 LEFT	FLOW SWITCH VALVE 9912194-2	*CF		V10F14 595	MTH 02-May-2002		O/C			
291011 RIGHT	FLOW SWITCH VALVE 9912194-2	*CF		V10F14 602	MTH 02-May-2002		O/C			
291012	SPEEDBRAKE DUMP VALVE 9912423-33	*CF		4082-6 181	MTH 02-May-2002		O/C			
291014	GEAR VALVE 9912423-35	*CF		4051-3 178	MTH 02-May-2002		O/C			
291015	LANDING GEAR VALVE 9912423-36	*CF		9504-1 178	MTH 02-May-2002		O/C			
291016 LEFT	SPEEDBRAKE CHECK VALVE 9912423-31	*CF		9505-1 355	MTH 02-May-2002		O/C			
291016 RIGHT	SPEEDBRAKE CHECK VALVE 9912423-31	*CF		9505-1 356	MTH 02-May-2002		O/C			
291017	THERMAL RELIEF VALVE 9912423-32	*CF		2577-1 178	MTH 02-May-2002		O/C			
291018	PNEUMATIC DUMP VALVE 9912423-34	*CF		9503-2 181	MTH 02-May-2002		O/C			
291019 LEFT	ATTENUATOR VALVE 9912423-28	*CF		4107-3 178	MTH 02-May-2002		O/C			
291019 RIGHT	ATTENUATOR VALVE 9912423-27	*CF		4107-4 178	MTH 02-May-2002		O/C			
291020	SPEED BRAKE VALVE 9912423-30	*CF		4052-3 184	MTH 02-May-2002		O/C			
291021	FLAP VALVE KMKE			9912423-29 4052	MTH 14-Dec-2016 HRS 3098.9 LDG 2687		O/C	0 0		
301001	ISOLATION VALVE 9912403-2	*CF		2602-36 0691	MTH 02-May-2002		O/C			
301002 LEFT	PRESSURE SWITCH 1106P55-1	*CF		1842A	MTH 02-May-2002		O/C			
301002 RIGHT	PRESSURE SWITCH 1106P55-1	*CF		1825A	MTH 02-May-2002		O/C			
301003 LEFT	PRESS REGULATOR VALVE 9912495-5	*CF		1962-00-9 1339	MTH 02-May-2002		O/C			
301003 RIGHT	PRESS REGULATOR VALVE 9912495-5	*CF		1962-00-9 1341	MTH 02-May-2002		O/C			
301004 LEFT	TEMPERATURE SWITCH SWF			1173T42-4 1681	MTH 02-May-2002 HRS 12		O/C	12		



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301004 RIGHT	TEMPERATURE SWITCH SWF			1173T42-4 1983	MTH 21-Sep-2002 HRS 162		O/C	0		
301005 LEFT	SOLENOID VALVE *CF			3D2353-06 N19238	MTH 02-May-2002		O/C			
301005 RIGHT	SOLENOID VALVE *CF			3D2353-06 N19258	MTH 02-May-2002		O/C			
301006 LEFT	HORIZONTAL STABILIZER BOOT KMKE			29S4D5244-15 NEG5180	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C	0 0		
301006 RIGHT	HORIZONTAL STABILIZER BOOT KMKE			29S4D5244-16 NEM6830	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C	0 0		
302001 LEFT	PRESS REG VALVE *CF			5285-00-3 169	MTH 02-May-2002		O/C			
302001 RIGHT	PRESS REG VALVE *CF			5285-00-3 170	MTH 02-May-2002		O/C			
302002 LEFT	INLET TEMP SWITCH *CF			1173T0759 1482	MTH 02-May-2002		O/C			
302002 RIGHT	INLET TEMP SWITCH *CF			1173T0759 1533	MTH 02-May-2002		O/C			
303002 LEFT	TUBE PITOT KMKE			PH502 2157011	MTH 01-Nov-2013 HRS 1816.7 LDG 1565		O/C	0 0 0		
303002 RIGHT	TUBE PITOT *CF			PH502 SN-UNKNOWN	MTH 02-May-2002		O/C			
304001	B/A TEMP MONITOR- *CF			1169-1 3153	MTH 02-May-2002		O/C			
304002	HEAT EXCHANGER 9912041-3 *CF			10653A 1324	MTH 02-May-2002		O/C			
304003	PRESSURE REGULATING CHECK VALVE 9912402-14 *CF			1962-00-3 1302	MTH 02-May-2002		O/C			
304004 AFT	FLOORBOARD TF006 SENSOR 9912085-3 *CF			27221274 12AU632	MTH 02-May-2002		O/C			
304004 FORWARD	T/C TT002 SENSOR 9912085-3 *CF			27221274 12AU628	MTH 02-May-2002		O/C			
304005	TEMP CONTROLLER 9912085-6 *CF			1E58-1 6AU95	MTH 02-May-2002		O/C			
304006	TEMP CONTROL VALVE 9912085-1 KMKE			27241287 5AU82P	MTH 14-Dec-2017 HRS 3565.4 LDG 3055 ACH 1184.1		O/C	0 0		
304007	ALCOHOL PUMP ASSY *CF			476411 SN-UNKNOWN	MTH 02-May-2002		O/C			
304008 LEFT	W/S BLEED AIR VALVE BYLB50168 *CF			1403-25 2449	MTH 02-May-2002		O/C			
304008 RIGHT	W/S BLEED AIR VALVE BYLB50168 *CF			1403-25 2857	MTH 02-May-2002		O/C			
304009	PRESSURE SWITCH *CF			1115P25 3725AB	MTH 02-May-2002		O/C			
304010 LEFT	PITOT STATIC CURRENT SENSOR *CF			76250-1 4657	MTH 02-May-2002		O/C			
304010 RIGHT	PITOT STATIC CURRENT SENSOR *CF			76250-1 4649	MTH 02-May-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
304013 LEFT	PITOT STATIC CURRENT SENSOR *CF			76250-1 NSN	MTH 02-May-2002		O/C			
304013 RIGHT	PITOT STATIC CURRENT SENSOR *CF			76250-1 NSN	MTH 02-May-2002		O/C			
312001 LEFT	DIGITAL CLOCK *CF			M877A5V 13145	MTH 02-May-2002		O/C			
313001	FLIGHT HOUR METER 85071 *CF			C664503-0104 SN-UNKNOWN	MTH 02-May-2002		O/C			
315001	CABIN ALT SWITCH 9910095-6	MKE		GB300NA161 1333034	MTH 13-Apr-2014 HRS 1973.7 LDG 1704		O/C	0 0 0		
315002	MASTER ANNUNCIATOR 9912586-2	MKE		9912586-2 586000247	MTH 22-Oct-2011 HRS 1208.5 LDG 1022		O/C			
321001 LEFT MAIN	(AND ATTACHING HARDWARE) LANDING GEAR *CF			6341200-1 71	MTH 02-May-2002		O/C			
321001 RIGHT MAIN	(AND ATTACHING HARDWARE) LANDING GEAR *CF			6341200-2 71	MTH 02-May-2002		O/C			
321003 LEFT MAIN GEAR	TRUNNION *CF			6341221-1 SN-UNKNOWN	MTH 02-May-2002 LDG 0		39991	0	39991	36445
321003 RIGHT MAIN GEAR	TRUNNION *CF			6341221-2 SN-UNKNOWN	MTH 02-May-2002 LDG 0		39991	0	39991	36445
<i>321004 : R</i>										
321004	FORK AND PISTON ASSEMBLY *CF			6342200-4 SN-UNKNOWN	MTH 02-May-2002 LDG 0		12500	0	12500	8954
321005 LEFT MAIN GEAR	OLEO ASSEMBLY *CF			6341201-1 146	MTH 02-May-2002 LDG 0		28075	0	28075	24529
321005 RIGHT MAIN GEAR	OLEO ASSEMBLY *CF			6341201-1 149	MTH 02-May-2002 LDG 0		28075	0	28075	24529
321007 LEFT	TRAILING LINK AND AXLE ASSEMBLY *CF			6341241-1 NSN	MTH 02-May-2002 LDG 0		41666	0	41666	38120
321007 RIGHT	TRAILING LINK AND AXLE ASSEMBLY *CF			6341241-2 NSN	MTH 02-May-2002 LDG 0		41666	0	41666	38120
321011 LEFT MAIN GEAR	OLEO ASSEMBLY LOWER BARREL KMKE			6390037-6 26477435F	MTH 02-May-2017 HRS 3245.3 LDG 2799 ACH 1065.3		16224	0	19023	15477
321011 RIGHT MAIN GEAR	OLEO ASSEMBLY LOWER BARREL *CF			6341135-3 NSN	MTH 02-May-2002 LDG 0		16224	0	16224	12678
321012 LEFT MAIN GEAR	OLEO ASSEMBLY UPPER BEARING ASSEMBLY *CF			6341133-9 NSN	MTH 02-May-2002 LDG 0		19713	0	19713	16167
321012 RIGHT MAIN GEAR	OLEO ASSEMBLY UPPER BEARING ASSEMBLY *CF			6341133-9 NSN	MTH 02-May-2002 LDG 0		19713	0	19713	16167
322001	NOSE LANDING GEAR SHIMMY DAMPER SWF			6343001-9 1849X	MTH 22-Apr-2005 HRS 586 LDG 424		O/C			0
322002	NOSE LANDING GEAR STRUT ASSY(AND ATTACHING HARDWARE) ASSEMBLY *CF			6342200-3 71	MTH 02-May-2002 LDG 0		22500	0	22500	18954
322005	NOSE LANDING GEAR ASSEMBLY *CF			6342200-2 71	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
323001 LEFT MAIN GEAR	SIDE BRACE ACTUATOR 9912573-2	*CF		1556700-3 0148	MTH 02-May-2002 LDG 0		41666	0	41666	38120
323001 RIGHT MAIN GEAR	SIDE BRACE ACTUATOR 9912573-2	*CF		1556700-3 0156	MTH 02-May-2002 LDG 0		41666	0	41666	38120
323002 LEFT MAIN GEAR	UPLOCK	KMKE		6327504-6 3930	MTH 18-Mar-2017 HRS 3167 LDG 2753 ACH 1065.3		O/C	0 0		
323002 RIGHT MAIN GEAR	UPLOCK	*CF		6327504-6 335	MTH 02-May-2002		O/C			
323004	NOSE GEAR ACTUATOR ASSEMBLY 9912370-4	*CF		1541900-5 0616	MTH 02-May-2002 LDG 0		12000	0	12000	8454
323005	NOSE LANDING GEAR UPLOCK ACTUATOR	*CF		6327504-7 180	MTH 02-May-2002		O/C			
323006	HYDRAULIC SHUTTLE VALVE	*CF		98312 203	MTH 02-May-2002		O/C			
323020	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912368-2	MKE		40005320-2 1488	MTH 13-Apr-2014 HRS 1973.7 LDG 1704		288	210	30-Sep-2020	19 m 3 d
Manufacture Date: 30-Sep-1996										
323021	EMERGENCY GEAR BOTTLE GAUGE	*CF		18225901 012032	MTH 02-May-2002		O/C			
324001 LEFT MAIN GEAR	WHEEL ASSEMBLY 9912743-6	KMKE		3-1601-3 0238	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C			
324001 RIGHT MAIN GEAR	WHEEL ASSEMBLY 9912743-6	KMKE		3-1601-3 1374	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C			
324002 NOSE LANDING GEAR	WHEEL ASSEMBLY	KMKE		3-1418 5466	MTH 28-Sep-2018 HRS 4003.4 LDG 3411		O/C			
324003 LEFT MAIN GEAR	TIRE 9912576-1	KMKE		026-528-0 8054S00379	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0		
324003 RIGHT MAIN GEAR	TIRE 9912576-1	KMKE		026-528-0 8057S00365	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0		
324004	NOSE LANDING GEAR TIRE	KMKE		184F68-1 73562415	MTH 28-Sep-2018 HRS 4003.4 LDG 3411		O/C	0 0		
324005 LEFT MAIN GEAR	BRAKE ASSEMBLY 9912743-5	KMKE		2-1651-1 0574	MTH 09-Jun-2017 HRS 3290.2 LDG 2838 ACH 1101.5		O/C	0 0		
324005 RIGHT MAIN GEAR	BRAKE ASSEMBLY 9912743-5	KMKE		2-1651-1 0202	MTH 13-May-2018 HRS 3805.4 LDG 3223		O/C			
324101	BRAKE ANTISKID VALVE 9912575-4	*CF		38-861-1 169	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324102 LEFT	ANTISKID TRANSDUCER 9912305-2	*CF		40-955 5839	MTH 02-May-2002		O/C			
324102 RIGHT	ANTISKID TRANSDUCER 9912305-2	*CF		40-955 5837	MTH 02-May-2002		O/C			
324103	DIGITAL BOX 9912575-3	*CF		142-031-1 180	MTH 02-May-2002		O/C			
324104	BRAKE PRESSURE SWITCH *CF			GPP1250-77 0145011	MTH 02-May-2002		O/C			
324105	PARKING BRAKE VALVE 9912388-1	*CF		95853 0671A	MTH 02-May-2002		O/C			
324106	HYDRAULIC PUMP MOTOR *CF			MP50B1 2235	MTH 02-May-2002		O/C			
324107	BRAKE ANTISKID ACCUMULATOR *CF			57C57663 0591	MTH 02-May-2002		O/C			
324108	LOW PRESSURE SWITCH 9912373-1	*CF		GPP1250-29 2235	MTH 02-May-2002		O/C			
324109	BRAKE PRESSURE PUMP 9912364-2	*CF		640929 1493	MTH 02-May-2002		O/C			
324110	EMERGENCY BRAKE VALVE MKE			878208-05 V061	MTH 22-Feb-2011 HRS 1008.4 LDG 855		O/C			
324111	FAULT DISPLAY UNIT 9912305-9	*CF		42-92750 1021A	MTH 02-May-2002		O/C			
324113	RELIEF VALVE *CF			1785-1 625	MTH 02-May-2002		O/C			
326001 LEFT MAIN GEAR	UPLOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 02-May-2002		O/C			
326001 NOSE LANDING GEAR	UPLOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 02-May-2002		O/C			
326001 RIGHT MAIN GEAR	UPLOCK SWITCH *CF			65-430087 SN-UNKNOWN	MTH 02-May-2002		O/C			
330000 LH	LANDING LIGHT BALLAST MKE			LSM-SCD-019-1 45534	MTH 31-Jul-2012 HRS 1434.2 LDG 1209		O/C	0 0 0		
330000 RH	LANDING LIGHT BALLAST MKE			LSM-SCD-019-1 45546	MTH 31-Jul-2012 HRS 1434.2 LDG 1209		O/C	0 0 0		
330001	INVERTER KVVV			SS120 1308	MTH 01-Oct-2014 HRS 2182.7 LDG 1884		O/C	0 0 0		
331001 CENTER	LIGHT DIMMER *CF			273-1 0150184	MTH 02-May-2002		O/C			
331001 LEFT	LIGHT DIMMER *CF			273-1 0150226	MTH 02-May-2002		O/C			
331001 RIGHT	LIGHT DIMMER *CF			273-1 0150156	MTH 02-May-2002		O/C			
331002	ELECTRICAL PANEL INVERTER *CF			EM2044-1 3569A	MTH 02-May-2002		O/C			
332001 L1	FORWARD LEFT INVERTER *CF			AL750PS 14249	MTH 02-May-2002		O/C			
332001 L2	MID FORWARD INVERTER *CF			AL750PS 14999	MTH 02-May-2002		O/C			
332001 L3	MID LEFT INVERTER *CF			AL750PS 15368	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
332001 L4	AFT MID INVERTER	KMKE		AL750PS 3433	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0		
332001 L5	AFT LEFT INVERTER	*CF		AL750PS 15547	MTH 02-May-2002		O/C			
332001 R1	FORWARD RIGHT INVERTER	*CF		AL750PS 15557	MTH 02-May-2002		O/C			
332001 R2	MID FORWARD INVERTER	*CF		AL750PS 15560	MTH 02-May-2002		O/C			
332001 R3	MID RIGHT INVERTER	KMKE		AL750PS 3607	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0		
332001 R4	AFT MID INVERTER	KMKE		AL750PS 3351	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0		
332001 R5	AFT RIGHT INVERTER	*CF		AL750PS 15571	MTH 02-May-2002		O/C			
334002	PULSE LIGHT CONTROL	KMKE		020P0023-1 AR01632	MTH 02-Nov-2012 HRS 1488.3 LDG 1264		O/C	0 0		
334003 LEFT	COLLISION LIGHT POWER SUPPLY	*CF	1	04-1502-1408 16835	MTH 02-May-2002		O/C			
334003 RIGHT	COLLISION LIGHT POWER SUPPLY	*CF	1	04-1502-1408 18145	MTH 02-May-2002		O/C			
334004 LEFT	LANDING LAMP HOUSING	*CF		50033025-1 1187	MTH 02-May-2002		O/C			
334004 RIGHT	LANDING LAMP HOUSING	*CF		50033025-1 1071	MTH 02-May-2002		O/C			
334005 LEFT	COLLISION LIGHT ASSEMBLY	*CF		03-1302-0003 18079	MTH 02-May-2002		O/C			
334005 RIGHT	COLLISION LIGHT ASSEMBLY	*CF		03-1302-0004 17764	MTH 02-May-2002		O/C			
334006	TAIL LIGHT ASSEMBLY	MKE		01-07090033-13 014088	MTH 28-Jun-2015 HRS 2518.4 LDG 2161		O/C			
334099 LEFT	LANDING LIGHT ASSEMBLY	KMKE		LSM-SCD-009-1 64873	MTH 29-Nov-2018 HRS 4093.5 LDG 3482		O/C	0 0 0		
334099 RIGHT	LANDING LIGHT ASSEMBLY	KMKE		LSM-SCD-009-1 64874	MTH 29-Nov-2018 HRS 4093.5 LDG 3482		O/C	0 0 0		
335000 LEFT	EMERGENCY EXIT LIGHT BATTERY	KMKE		CBS28-1 1185M	MTH 18-Mar-2017 HRS 3167 LDG 2753 ACH 1065.3		O/C			
341001 LEFT	AIR DATA DISPLAY UNIT ADC-3000	*CF	3	822-1109-004 J5PF	MTH 02-May-2002		O/C			
341001 RIGHT	AIR DATA DISPLAY UNIT ADC-3000	KMKE		822-1109-004 HTRC	MTH 05-Aug-2011 HRS 1169.7 LDG 975		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
341002 STANDBY	ALTIMETER/AIRSPEED INDICATOR	KMKE		WL102AMS6 AP356	MTH 20-Jan-2017 HRS 3136.3 LDG 2716 ACH 1061.3		O/C	1 0		
341003	AOA INDEXER	*CF	A	C12463-3 391	MTH 02-May-2002		O/C			
341004	AOA DISPLAY UNIT	*CF		C-13206-1 179	MTH 02-May-2002		O/C			
341006	AOA INDICATOR	*CF		C12405-1 684	MTH 02-May-2002		O/C			
341007	AOA SENSOR	*CF		C-12717-1 767	MTH 02-May-2002		O/C			
341008	BAROMETRIC SWITCH	*CF		GBC300-156 0148076	MTH 02-May-2002		O/C			
341010 AFT	RADIO ALT ANTENNA	*CF		S67-2002 23810	MTH 02-May-2002		O/C			
341010 FORWARD	RADIO ALT ANTENNA	*CF		S67-2002 23808	MTH 02-May-2002		O/C			
341011	RADIO ALTIMETER TRANSMITTER ALT-55	*CF	11	622-2855-011 J62R	MTH 02-May-2002		O/C			
341012	RADIO ALT CONVERTER RAC-870	*CF	5	622-7209-002 HXWB	MTH 02-May-2002		O/C			
341030	TEMPERATURE PROBE SENSOR	*CF		0129G A38226	MTH 02-May-2002		O/C			
341101	IAPS CARD CAGE ICC-3001	*CF		822-1459-001 J26H	MTH 02-May-2002		O/C			
341102 LEFT	IO PROCESSOR CARD ICO-3000	*CF		822-1130-151 H6MK	MTH 02-May-2002		O/C			
341102 RIGHT	IO PROCESSOR CARD IOC-3000	*CF		822-1130-151 HGNY	MTH 02-May-2002		O/C			
341103 NO. 1	CONFIGURATION CONTROL STRAPPING UNIT			822-1363-002 HW7G	MTH 02-May-2002		O/C			
341103 NO. 2	CONFIGURATION CONTROL STRAPPING UNIT			822-1363-002 HLHW	MTH 02-May-2002		O/C			
342002 LEFT	AHRS DISPLAY UNIT AHC-3000	MKE	1	822-1110-002 HJ2C	MTH 31-Jul-2012 HRS 1434.2 LDG 1209		O/C	1434.2		
342002 RIGHT	AHRS DISPLAY UNIT AHC-3000	MKE	1	822-1110-002 HL4T	MTH 31-Jul-2012 HRS 1434.2 LDG 1209		O/C	1434.2		
342003	STANDBY HSI INDICATOR S3100-303	KMKE		2855-01-1 550	MTH 15-Dec-2013 HRS 1864.1 LDG 1603		O/C			
342005 LEFT	FLIGHT GUIDANCE DISPLAY UNIT FGC-3000	SWF		822-1108-122 J2FK	MTH 22-Apr-2005 HRS 586		O/C	0		
342005 RIGHT	FLIGHT GUIDANCE DISPLAY UNIT FGC-3000	SWF		822-1108-122 HYKY	MTH 22-Apr-2005 HRS 586		O/C	0		
342006 LEFT	FLUX DETECTION UNIT FDU-3000	MKE		822-1193-001 25998	MTH 13-Apr-2014 HRS 1973.7 LDG 1704		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
342006	FLUX DETECTION UNIT			822-1193-001	MTH 12-May-2014		O/C	0		
RIGHT	FDU-3000	KMKE		302354	HRS 2026.5			0		
					LDG 1736			0		
342007	EXTERNAL COMPENSATION UNIT			822-1200-003	MTH 02-May-2002		O/C			
LEFT	ECU-3000	*CF		HWLX						
342007	EXTERNAL COMPENSATION UNIT			822-1200-003	MTH 02-May-2002		O/C			
RIGHT	ECU-3000	*CF		HXTY						
342008	IAPS POWER SUPPLY		6	822-1137-001	MTH 02-May-2002		O/C			
LEFT	PWR-3000	*CF		J21Y						
342008	IAPS POWER SUPPLY		6	822-1137-001	MTH 02-May-2002		O/C			
RIGHT	PWR-3000	*CF		HXLP						
342009	ENVIROMENTAL CONTROL		2	822-1167-001	MTH 02-May-2002		O/C			
	IEC-3001	*CF		HTDT						
342010	OPERATION CONFIGURATION MODULE				MTH 02-May-2002		O/C			
LEFT	OCM-3100	*CF		822-1484-201						
				HTLY						
342010	OPERATION CONFIGURATION MODULE				MTH 02-May-2002		O/C			
RIGHT	OCM-3100	*CF		822-1484-201						
				HTLW						
342030	STANDBY GYRO			501-1568-56	MTH 23-Sep-2002		O/C			
	AI-300AE	SWF		3010	HRS 162			0		
342031	STANDBY GYRO POWER SUPPLY			501-1682-01	MTH 09-Dec-2016		O/C			
	PS-834A	KMKE	5	1990	HRS 3091.8					
					LDG 2681					
					ACH 1036.8					
342301	MODE SELECTOR	*CF	10	622-6209-019	MTH 02-May-2002		O/C			
LEFT	MSP-85			HWYJ						
342301	MODE SELECTOR	ICT	10	622-6209-019	MTH 10-May-2002		O/C			
RIGHT	MSP-85			NHJD	HRS 13			0		
342302	ADAPTIVE FLT DISPLAY			822-1084-206	MTH 22-Feb-2018		O/C	0		
CENTER		KMKE		10PRY	HRS 3666.6			0		
					LDG 3132					
342302	ADAPTIVE FLT DISPLAY			822-1084-206	MTH 08-Aug-2006		O/C			
LEFT		HPN		123MY	HRS 719			0		
342302	MULTI-FUNCTION FLT DISPLAY			822-1084-206	MTH 22-Sep-2013		O/C	0		
RIGHT		KMKE	3	HM4H	HRS 1772.8			0		
					LDG 1535			0		
342303	COURSE PANEL	*CF		822-1281-002	MTH 02-May-2002		O/C			
	CKP-3000			HXBB						
342304	DISPLAY CONTROL PANEL		1	822-1134-102	MTH 02-May-2002		O/C			
LEFT	DCP-3000	*CF		J06V						
342304	DISPLAY CONTROL PANEL		1	822-1134-102	MTH 02-May-2002		O/C			
RIGHT	DCP-3000	*CF		H04Y						
342305	COURSE/HEADING PANEL	*CF		822-1279-002	MTH 02-May-2002		O/C			
	CHP-3000			HXTW						
343000	MARKER BEACON RECEIVER		1	066-01044-0001	MTH 02-May-2002		O/C			
	KMR-675	*CF		1646						
343001	MARKER BEACON ANTENNA			31-10-01	MTH 02-May-2002		O/C			
		*CF		4141						
343002	DUAL GLIDESCOPE COUPLER			82-70-01	MTH 02-May-2002		O/C			
		*CF		1256						



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
343003	GLIDESCOPE ANTENNA *CF			RGS10-48 A8333	MTH 02-May-2002		O/C			
344001	EGPWS DISPLAY UNIT S2800-497	SWF		965-0976-040-213-213 1960	MTH 21-Sep-2002 HRS 162		O/C	0		
344002	RADAR TRANSCIEVER RTA-800	*CF	30	822-1050-004 HJ2R	MTH 02-May-2002		O/C			
344011	STORMSCOPE PROCESSOR WX-1000E	KMKE	3	78-8060-6086-5 JFP107C3391	MTH 25-Jul-2018 HRS 3894.9 LDG 3303		O/C			
344012	STORMSCOPE ANTENNA WX-1000E	MKE		78-8051-9200-8 83730	MTH 11-Dec-2015 HRS 2675.8 LDG 2304 ACH 897.7		O/C	0 0		
345001 FORWARD	DME 1 ANTENNA *CF			56-80-01 8147	MTH 02-May-2002		O/C			
345002 LEFT	DME 1 TRANSCIEVER KN-63	*CF	6	066-01070-0001 27193	MTH 02-May-2002		O/C			
345003 LEFT	DME INDICATOR KDI-574	*CF		066-01069-0014 84125	MTH 02-May-2002		O/C			
345004 LEFT	DME CONVERTER KDA-689	*CF	1	071-01227-0001 10936	MTH 02-May-2002		O/C			
345005 LEFT	NAVIGATION ANTENNA *CF	KMKE		CI120-1-L 527163	MTH 09-Dec-2016 HRS 3091.8 LDG 2681 ACH 1036.8		O/C	0 0		
345005 RIGHT	NAVIGATION ANTENNA *CF	KMKE		CI120-1-L 527164	MTH 09-Dec-2016 HRS 3091.8 LDG 2681 ACH 1036.8		O/C	0 0		
345006 BOTTOM	VHF NAV 2 RECEIVER KN-53 S3100-33	*CF	11	066-01067-0004 83066	MTH 02-May-2002		O/C			
345006 TOP	VHF NAV 1 RECEIVER KN-53 S3100-33	*CF	11	066-01067-0004 83100	MTH 02-May-2002		O/C			
345007	DUAL NAV CONVERTER KN-40 S3100-19	*CF	7	066-01130-0701 12182	MTH 02-May-2002		O/C			
345020 TOP	ADF 1 ANTENNA KA-44B	*CF		071-01234-0002 77297	MTH 02-May-2002		O/C			
345021	ADF 1 RECEIVER KR-87	*CF		066-01072-0006 76374	MTH 02-May-2002		O/C			
345039	GPS 1 ANTENNA			PN SN-UNKNOWN	MTH 02-May-2002		O/C	0		
345040 AFT	TRANSPONDER 2 ANTENNA 85226	*CF		DMNI50-2-2 82763	MTH 02-May-2002		O/C			
345040 FORWARD	TRANSPONDER 1 ANTENNA 85226	*CF		DMNI50-2-2 82948	MTH 02-May-2002		O/C			
345041 NO. 1	TRANSPONDER	KMKE		89000067-002002 02873	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0		
345041 NO. 2	TRANSPONDER	KMKE		89000067-002002 02875	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345049	FMS NAV DISPLAY UNIT S3100-259/UNSIL	KMKE		2116-40-1110 196	MTH 21-Jun-2018 HRS 3859.7 LDG 3266		O/C			
345050	GPS FMS DISPLAY S3100-241	KMKE	8	1117-1-104 6614	MTH 27-Sep-2016 HRS 2996.6 LDG 2588		O/C	0 0		
345051 NO. 1	GPS FMS ANTENNA	KMKE		071-01620-0001 49311548	MTH 11-Feb-2019 HRS 4167.1 LDG 3536		O/C	0 0 0		
345052	FMS CONFIGURATION MODULE *CF			11921 SN-UNKNOWN	MTH 02-May-2002		O/C			
345053	DATA TRANSFER UNIT PERMANENT DTU-100		1	1406-01-1 1663	MTH 02-May-2002		O/C			
345060	CONTROLLER TCAS CP-66B		*CF	071-01568-1801 2445	MTH 02-May-2002		O/C			
345061	TCAS PROCESSOR TPU-66A S3100-53	KMKE		066-01145-0101 2541	MTH 22-Jul-2017 HRS 3335.1 LDG 2882 ACH 1124.8		O/C			
345062 BOTTOM	TCAS ANTENNA ANT-67A		*CF	071-01548-0200 8955	MTH 02-May-2002		O/C			
345062 TOP	TCAS ANTENNA ANT-67A		*CF	071-01548-0200 9010	MTH 02-May-2002		O/C			
346050	E.L. PANEL		*CF	050-03104-0000 1964	MTH 02-May-2002		O/C			
350006	OXYGEN CYLINDER PURITAN/DOT-E8162-1850	KMKE		176274-50 673177801	MTH 16-May-2015 HRS 2474.7 LDG 2119		180		28-Feb-2030	132 m 1 d
Manufacture Date: 01-Feb-2015										
350007	OXYGEN PRESSURE GAUGE MD-97		*CF	C668512-0101 M21094	MTH 02-May-2002		O/C			
351001	OXYGEN 3 POSITION VALVE 9912057-21		*CF	110081-06 0752	MTH 02-May-2002		O/C			
351002 COPILOT	OXYGEN MASK 9914067-41	KMKE		MC10-16-101 100250	MTH 24-Nov-2014 HRS 2265.1 LDG 1945		72	0	30-Nov-2020	21 m 3 d
351002 PILOT	OXYGEN MASK 9914067-41	KMKE		MC10-16-101 121031	MTH 24-Nov-2014 HRS 2265.1 LDG 1945		72	0	30-Nov-2020	21 m 3 d
351003	OXYGEN PRESSURE SWITCH *CF			P24032 502	MTH 02-May-2002		O/C			
361001 LEFT	PRECOOL TEMPERATURE SENSOR 9912584-3		*CF	27431501-10 12AU94	MTH 02-May-2002		O/C			
361001 RIGHT	PRECOOL TEMPERATURE SENSOR 9912584-3		*CF	27431501-10 12AU95	MTH 02-May-2002		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY 9914402-4	KMKE		8161-2 S4883-T1481	MTH 31-Jan-2016 HRS 2731.2 LDG 2344		108 3500	0 0	31-Jan-2025 6231.2	71 m 4 d 2052.9
361002 RIGHT	B/A PRECOOLER ASSEMBLY 9914402-4	KMKE		8161-2 S4883-T1473	MTH 31-Jan-2016 HRS 2731.2 LDG 2344		108 3500	0 0	31-Jan-2025 6231.2	71 m 4 d 2052.9
361003 LEFT	MODULATING VALVE 9912584-1		*CF	1H139-1 11AU42	MTH 02-May-2002		O/C			
361003 RIGHT	MODULATING VALVE 9912584-2		*CF	1H139-2 10AU44	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361005	PRESSURE SWITCH	*CF		P18M30 2897	MTH 02-May-2002		O/C			
361006 LEFT	OVERTEMPERATURE SWITCH 9914149-2	*CF		1173T181-2 3134	MTH 02-May-2002		O/C			
361006 RIGHT	OVERTEMPERATURE SWITCH 9914149-2	*CF		1173T181-2 3346	MTH 02-May-2002		O/C			
361007	B/A PRESSURE REGULATOR 9912510-1	*CF		1H75-18 11AU150	MTH 02-May-2002		O/C			
521001	CABIN DOOR ASSEMBLY			PN SN-UNKNOWN	MTH 02-May-2002		O/C	0		
522001	INFLATABLE DOOR SEAL 9912075-4	*CF		S15501-4 SN-UNKNOWN	MTH 02-May-2002		O/C			
522002	SECONDARY SEAL	MKE		PN SN-UNKNOWN	MTH 18-May-2014 HRS 2038.1 LDG 1744		O/C	0 0 0		
530000	RADOME ASSEMBLY	KMKE		6313101-847-1 115	MTH 09-Jun-2017 HRS 3290.2 LDG 2838 ACH 1101.5		O/C			
531000 LEFT	TRUNNION SUPPORT FITTING *CF			5513056-5 SN-UNKNOWN	MTH 02-May-2002 LDG 0		22500	0	22500	18954
531000 RIGHT	TRUNNION SUPPORT FITTING *CF			5513056-6 SN-UNKNOWN	MTH 02-May-2002 LDG 0		22500	0	22500	18954
531001	NOSE LANDING GEAR ACTUATOR FITTING *CF			6511105-1 SN-UNKNOWN	MTH 02-May-2002 LDG 0		23900	0	23900	20354
561001 LEFT	WINDSHIELD ASSY, (LH) 9912064-15	*CF		P00042-1 234	MTH 02-May-2002		O/C			
561001 RIGHT	WINDSHIELD ASSY, (LH) 9912064-16	*CF		P00042-2 256	MTH 02-May-2002		O/C			
561002 L1	CABIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 L2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 L3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 L4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 L5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 L6	CABIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 R1	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 R2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 R3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 R4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 R5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			
561002 R6	CABIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
561003 LEFT	PILOT SIDE WINDOW	MKE		6311065-27 11WZ5-01	MTH 11-Dec-2015 HRS 2675.8 LDG 2304 ACH 897.7		O/C	0		
561004 RIGHT	CO-PILOT SIDE WINDOW	MKE		6311065-26 11WA0-01	MTH 11-Dec-2015 HRS 2675.8 LDG 2304 ACH 897.7		O/C	0		
571000 LEFT	AFT TRUNNION ATTACH FITTING	*CF		6321070-5 SN-UNKNOWN	MTH 02-May-2002 LDG 0		20480	0	20480	16934
571000 RIGHT	AFT TRUNNION ATTACH FITTING	*CF		6321070-6 SN-UNKNOWN	MTH 02-May-2002 LDG 0		20480	0	20480	16934
571001 LEFT	FORWARD TRUNNION ATTACH FITTING	*CF		6321060-5 SN-UNKNOWN	MTH 02-May-2002 LDG 0		20480	0	20480	16934
571001 RIGHT	FORWARD TRUNNION ATTACH FITTING	*CF		6321060-6 SN-UNKNOWN	MTH 02-May-2002 LDG 0		20480	0	20480	16934
571002 LEFT	SIDE BRACE FITTING	*CF		6321080-1 SN-UNKNOWN	MTH 02-May-2002 LDG 0		35000	0	35000	31454
571002 RIGHT	SIDE BRACE FITTING	*CF		6321080-2 SN-UNKNOWN	MTH 02-May-2002 LDG 0		35000	0	35000	31454
712001 LEFT ENGINE FORWARD BOTTOM	MOUNT ASSEMBLY	*CF		LM601SA5 9912410-3 3050	MTH 02-May-2002 HRS 0		DUE DUE DUE	0	4473.7	295.4
712001 LEFT ENGINE FORWARD TOP	MOUNT ASSEMBLY	*CF		LM601SA5 9912410-3 3040	MTH 02-May-2002 HRS 0		DUE DUE DUE	0	4473.7	295.4
712001 RIGHT ENGINE FORWARD BOTTOM	MOUNT ASSEMBLY	*CF		LM601SA5 9912410-3 3034	MTH 02-May-2002 HRS 0		DUE DUE DUE	0	4483.9	305.6
712001 RIGHT ENGINE FORWARD TOP	MOUNT ASSEMBLY	*CF		LM601SA5 9912410-3 3018	MTH 02-May-2002 HRS 0		DUE DUE DUE	0	4483.9	305.6
712002 LEFT ENGINE AFT	MOUNT ASSEMBLY	*CF		LM601SA4 9912410-2 SN-UNKNOWN	MTH 02-May-2002 HRS 0		DUE DUE DUE	0	4473.7	295.4
712002 RIGHT ENGINE AFT	MOUNT ASSEMBLY	*CF		LM601SA4 9912410-2 SN-UNKNOWN	MTH 02-May-2002 HRS 0		DUE DUE DUE	0	4483.9	305.6
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE	*CF		60500 FJ44-2C 1143	MTH 02-May-2002		E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE	*CF		60500 FJ44-2C 1108	MTH 02-May-2002		E/C			
720001 E1	FAN ROTOR	*CF		61967 AU01284	MTH 02-May-2002 LDG 0		10000	0	10000	6454
720001 E2	FAN ROTOR	*CF		61967 AU01257	MTH 02-May-2002 LDG -6	2	10000	0	9996	6450
720002 E1	IP COMPRESSOR ROTOR	*CF		61968 AU01323	MTH 02-May-2002 LDG 0		8000	0	8000	4454
720002 E2	IP COMPRESSOR ROTOR	*CF		61968 AU01251	MTH 02-May-2002 LDG -6	2	8000	0	7996	4450
720003 E1	COMPLETE LP SHAFT ASSEMBLY	*CF		64257 RX1SN9037	MTH 02-May-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
720003 E2	COMPLETE LP SHAFT ASSEMBLY *CF			64257 RX1SN9017	MTH 02-May-2002		O/C			
720004 E1	HIGH PRESSURE SHAFT *CF			64711 AU00514	MTH 02-May-2002		O/C			
720004 E2	HIGH PRESSURE SHAFT *CF			64711 AU00449	MTH 02-May-2002		O/C			
720005 E1	HP COMPRESSOR COVER *CF			65593 AU01721	MTH 02-May-2002		O/C			
720005 E2	HP COMPRESSOR COVER *CF			65593 AU01514	MTH 02-May-2002		O/C			
720006 E1	DIFFUSER CASE ASSEMBLY *CF			67894 AU01355	MTH 02-May-2002		O/C			
720006 E2	DIFFUSER CASE ASSEMBLY *CF			60483 AU01282	MTH 02-May-2002		O/C			
720007 E1	1ST LP TURBINE NOZZLE SWF			60240 AU01628	MTH 17-Sep-2002 HRS 162		O/C	0		
720007 E2	1ST LP TURBINE NOZZLE MKE			115316 AU01211	MTH 03-Apr-2014 HRS 1973.7 LDG 1704		O/C	3252.7 7256		
720008 E1	ACCESSORY DRIVE GEARBOX ASSEMBLY KMKE			120746 AU20158	MTH 31-Mar-2016 HRS 2828.7 LDG 2433		O/C			
720008 E2	ACCESSORY DRIVE GEARBOX ASSEMBLY KMKE			120746 AU20698	MTH 31-Mar-2016 HRS 2828.7 LDG 2433		O/C			
725101 E1	HP COMPRESSOR ROTOR *CF			61964 HW12161	MTH 02-May-2002 LDG 0		6000	0	6000	2454
725101 E2	HP COMPRESSOR ROTOR *CF			61964 LC2616	MTH 02-May-2002 LDG -6	2	6000	0	5996	2450
725102 E1	HP TURBINE ROTOR *CF			64411 RRL0291	MTH 02-May-2002		O/C			
725102 E2	HP TURBINE ROTOR *CF			64411 RRL0284	MTH 02-May-2002		O/C			
725103 E1	HP TURBINE DISK *CF			59387 RRL7LD12031	MTH 02-May-2002 LDG 0		8000	0	8000	4454
725103 E2	HP TURBINE DISK *CF			59387 RRL7LD11780	MTH 02-May-2002 LDG -6	2	8000	0	7996	4450
725501 E1	1ST LP TURBINE DISK *CF			55531 RRL7S01680	MTH 02-May-2002 LDG 0		10000	0	10000	6454
725501 E2	1ST LP TURBINE DISK *CF			55531 RRL7S01402	MTH 02-May-2002 LDG -6	2	10000	0	9996	6450
725502 E1	2ND LP TURBINE DISK *CF			55534 RRL7S01835	MTH 02-May-2002 LDG 0		10000	0	10000	6454
725502 E2	2ND LP TURBINE DISK *CF			55534 RRL7S01621	MTH 02-May-2002 LDG -6	2	10000	0	9996	6450
730001 LEFT	FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 5544	MTH 02-May-2002		O/C			
730001 RIGHT	FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 5315	MTH 02-May-2002		O/C			
733001 LEFT	FUEL FLOW TRANSMITTER 9912417-1 *CF			1573-4 1215	MTH 02-May-2002		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9912417-1 *CF			1573-4 1224	MTH 02-May-2002		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
730002 E1	FUEL NOZZLE ASSEMBLY	KMKE		50817 BCC-00001445	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C			
730002 E2	FUEL NOZZLE ASSEMBLY	KMKE		50817 BCC-AAA26823	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C			
730003 E1	SEAL AND FUEL SLINGER	*CF		55608 AU02621	MTH 02-May-2002		O/C			
730003 E2	SEAL AND FUEL SLINGER	MKE		55608 AU02701	MTH 03-Apr-2014 HRS 1973.7 LDG 1704		O/C			
731046 E1	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 02-May-2002		O/C	0		
731046 E2	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 02-May-2002		O/C	0		
732101 E1	INTEGRATED FUEL CONTROL UNIT	KMKE		115002 RF12365656	MTH 13-Sep-2018 HRS 3985.7 LDG 3391		4000	0	7985.7	3807.4
732101 E2	INTEGRATED FUEL CONTROL UNIT	KMKE		8063-757 RF13349008	MTH 11-Oct-2017 HRS 3437.9 LDG 2973		4000	117	7320.9	3142.6
732301 E1	FUEL FILTER ELECTRICAL INDICATOR	MKE		57847 GE-3046	MTH 03-Apr-2014 HRS 1973.7 LDG 1704		O/C			
732301 E2	FUEL FILTER ELECTRICAL INDICATOR	MKE		57847 GE-1488	MTH 03-Apr-2014 HRS 1973.7 LDG 1704		O/C			
741001 E1 INBOARD	IGNITION EXCITER	*CF		CH92007 CK0101291	MTH 02-May-2002		O/C			
741001 E1 OUTBOARD	IGNITION EXCITER	KMKE		68145 CK1500055	MTH 31-Mar-2016 HRS 2828.7 LDG 2433		O/C	0	0	
741001 E2 INBOARD	IGNITION EXCITER	SWF		68145 CK0100723	MTH 22-Apr-2005 HRS 586		O/C	0		
741001 E2 OUTBOARD	IGNITION EXCITER	*CF		CH92007 CK0100548	MTH 02-May-2002		O/C			
741002 E1	SHORT IGNITER LEAD	*CF		53279 SN-UNKNOWN	MTH 02-May-2002		O/C			
741002 E2	SHORT IGNITER LEAD	*CF		53279 SN-UNKNOWN	MTH 02-May-2002		O/C			
741003 E1	LONG IGNITER LEAD	*CF		53221 SN-UNKNOWN	MTH 02-May-2002		O/C			
741003 E2	LONG IGNITER LEAD	SWF		53221 SN-UNKNOWN	MTH 12-Jun-2003 HRS 293		O/C	0		
741004 E1 INBOARD	IGNITOR	KMKE		68032 CK-1801115	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C			
741004 E1 OUTBOARD	IGNITOR	KMKE		68032 CK-1801110	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
741004 E2 INBOARD	IGNITOR	KMKE		68032 CK-1801111	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C			
741004 E2 OUTBOARD	IGNITOR	KMKE		68032 CK-1801107	MTH 14-Oct-2018 HRS 4022.4 LDG 3426		O/C			
761001	ENGINE SYNC CONTROLLER *CF			213693 13181841	MTH 02-May-2002		O/C			
761002	ENGINE SYNC ACTUATOR *CF			5485-066 13149886	MTH 02-May-2002		O/C			
772001 LEFT NO. 1	ITT PROBE *CF			62141 YYF006157	MTH 02-May-2002		O/C			
772001 LEFT NO. 2	ITT PROBE *CF			62141 YYF006158	MTH 02-May-2002		O/C			
772001 LEFT NO. 3	ITT PROBE *CF			62141 YYF006159	MTH 02-May-2002		O/C			
772001 LEFT NO. 4	ITT PROBE *CF			62141 YYF006160	MTH 02-May-2002		O/C			
772001 LEFT NO. 5	ITT PROBE *CF			62141 YYF006161	MTH 02-May-2002		O/C			
772001 LEFT NO. 6	ITT PROBE *CF			62141 YYF006162	MTH 02-May-2002		O/C			
772002 RIGHT NO. 1 <i>772001 : E2-1</i>	ITT PROBE *CF	KMKE		62141 SN-UNKNOWN	MTH 20-Aug-2016 HRS 2963.5 LDG 2545		O/C	0 0 0		
772002 RIGHT NO. 2 <i>772001 : E2-2</i>	ITT PROBE *CF	KMKE		62141 SN-UNKNOWN	MTH 20-Aug-2016 HRS 2963.5 LDG 2545		O/C	0 0 0		
772002 RIGHT NO. 3 <i>772001 : E2-3</i>	ITT PROBE *CF	KMKE		62141 SN-UNKNOWN	MTH 20-Aug-2016 HRS 2963.5 LDG 2545		O/C	0 0 0		
772002 RIGHT NO. 4 <i>772001 : E2-4</i>	ITT PROBE *CF	KMKE		62141 SN-UNKNOWN	MTH 20-Aug-2016 HRS 2963.5 LDG 2545		O/C	0 0 0		
772002 RIGHT NO. 5 <i>772001 : E2-5</i>	ITT PROBE *CF	KMKE		62141 SN-UNKNOWN	MTH 20-Aug-2016 HRS 2963.5 LDG 2545		O/C	0 0 0		
772002 RIGHT NO. 6 <i>772001 : E2-6</i>	ITT PROBE *CF	KMKE		62141 SN-UNKNOWN	MTH 20-Aug-2016 HRS 2963.5 LDG 2545		O/C	0 0 0		
774001	N1 STANDBY INDICATOR *CF			10645N01R02 0309A	MTH 02-May-2002		O/C			
774002 LEFT AFT <i>774002A : L</i>	CONCENTRATOR UNIT DCU-3010 *CF			822-1278-002 FTWX	MTH 02-May-2002		O/C			
774002 LEFT FORWARD	CONCENTRATOR UNIT DCU-3010 *CF			822-1278-002 J07W	MTH 02-May-2002		O/C			
774002 RIGHT AFT <i>774002A : R</i>	CONCENTRATOR UNIT DCU-3010 *CF			822-1278-002 J07R	MTH 02-May-2002		O/C			
774002 RIGHT FORWARD	CONCENTRATOR UNIT DCU-3010 *CF			822-1278-002 J1XL	MTH 02-May-2002		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
771001 E1	N1 SPEED PICKUP	*CF		50867 YYV1074	MTH 02-May-2002		O/C			
771001 E2	N1 SPEED PICKUP	*CF		50867 YYV977	MTH 02-May-2002		O/C			
771002 E1	N2 SPEED PICKUP	MKE		70721 YYV760	MTH 02-Apr-2011 HRS 1077.7 LDG 889		O/C	0 0		
771002 E2	N2 SPEED PICKUP	*CF		50866 YYV942	MTH 02-May-2002		O/C			
772002 E2	ITT HARNESS	KMKE		75378 YYF003214	MTH 20-Aug-2016 HRS 2963.5 LDG 2545		O/C	0 0 0		
783000 LEFT	T/R DEPLOY SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
783000 RIGHT	T/R DEPLOY SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
783001 LEFT	T/R STOW SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
783001 RIGHT	T/R STOW SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 02-May-2002		O/C			
783003 LEFT	ATTENUATOR ACTUATOR	*CF		6317105-13 402	MTH 02-May-2002		O/C			
783003 RIGHT	ATTENUATOR ACTUATOR	*CF		6317105-13 407	MTH 02-May-2002		O/C			
793002 LEFT ENGINE	OIL PRESSURE SWITCH	*CF		S1103P89-3 1259	MTH 02-May-2002		O/C			
793002 RIGHT ENGINE	OIL PRESSURE SWITCH	RAP		S1103P89-3 1600	MTH 19-Jul-2003 HRS 328		O/C	0		
793003 LEFT ENGINE	OIL PRESSURE TRANSMITTER	*CF		APTE-304-200G 66195351	MTH 02-May-2002		O/C			
793003 RIGHT ENGINE	OIL PRESSURE TRANSMITTER	*CF		APTE-304-200G 66195353	MTH 02-May-2002		O/C			
792201 E1	LUBE OIL COOLER	*CF		59857 FC0299	MTH 02-May-2002		O/C			
792201 E2	LUBE OIL COOLER	*CF		59857 FC0242	MTH 02-May-2002		O/C			
792401 E1	LUBE AND SCAVENGE PUMP	*CF		63123 WL01306	MTH 02-May-2002 HRS 0		5000	0	5000	821.7
792401 E2	LUBE AND SCAVENGE PUMP	*CF		63123 WL01136	MTH 02-May-2002 HRS -10.2		5000	0	4989.8	811.5
801101 LEFT ENGINE	STARTER GENERATOR	KMKE		300SGL129Q S00444	MTH 26-Aug-2018 HRS 3955.1 LDG 3358		1000	0	4955.1	776.8
801101 RIGHT ENGINE	STARTER GENERATOR	KMKE		300SGL129Q S7249KL2	MTH 26-Aug-2018 HRS 3955.1 LDG 3358		1000	0	4955.1	776.8



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED MTH			-			
	MOC :									
SL 525A-99-01 R04	CESCOM PRICES (THIS SL CANCELS SL525A-99-01 R3 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 525A-99-03	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 525A-99-04	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 525A-03-01 R01	SUPPLEMENTAL TYPE CERTIFICATION (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	MOC :									
SL 525A-99-06	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 525A-05-02	PRECOOLER LIFE LIMIT			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 R01 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R02)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 E1	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
	MOC :									
SB FJ44-05-002 E2	UNSERVICEABLE PARTS - NOTIFICATION (SUPERSEDED BY FJ44-05-002 R01)			INFORMATIONAL			-			
	MOC :									
SB 525A-11-02 11SB-02	ENGINE OIL QUANTITY PLACARD REPLACEMENT	SWF		RECOMMENDED	MTH 12-Mar-2004 HRS 451		-			Complete
	MOC :	COMPLIED WITH								
SB 525A-11-04 11SB-04	GEAR EXTEND SPEED REDUCTION	HPN		MANDATORY	MTH 01-Nov-2006 HRS 747		A/R			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL 525A-20-01 R09	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
	MOC :									
SL 525A-20-03	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SB 525A-21-05 21SB-05	TEMPERATURE SENSOR RELOCATION	MKE		OPTIONAL	MTH 22-Feb-2011 HRS 1008.4 LDG 855		A/R			Complete
	MOC :									
SB 525A-21-06	AIR CONDITIONING - AFT EVAPORATOR DRAIN HOSE IMPROVEMENT			DISCRETIONARY			A/R			
	MOC :									
SB 525A-23-04 23SB-04	HONEYWELL KY-196A/KY-196B DUAL VHF COMMUNICATION SYSTEM UPGRADE	SWF		RECOMMENDED	MTH 22-Apr-2005 HRS 586		-			Complete
	MOC :									
SB 525A-23-05 23SB-05	GARMIN RADIO REPLACEMENT			OPTIONAL	MTH		-			
	MOC :									
SB 525A-23-07 23SB-07	GARMIN GTX330/330D TRANSPONDER SOFTWARE VERSION 3.03 UPGRADE	SWF		MANDATORY	MTH 22-Apr-2005 HRS 586		-			N/A
	MOC :									
SB 525A-24-02 24SB-02	AFT CABIN WIRE BUNDLE PROTECTION	SWF		RECOMMENDED	MTH 22-Apr-2005 HRS 586		-			Complete
	MOC :									
SB 525A-24-03 24SB-03	AVIONICS EMERGENCY BUS RELAY IMPROVEMENT	MKE		DISCRETIONARY	MTH 22-Feb-2011 HRS 1008.4 LDG 855		A/R			Complete
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525A-24-06	GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING	MKE		MTH HRS LDG	26-May-2013 1636.2 1391		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SB525A-24-06 DATED FEBRUARY 15, 2013; GENERATOR CONTROL UNIT WIRE BUNDLE ROUTING.										
SL 525A-24-02 24SL-02	WIRE BUNDLE INSPECTION	MKE		RECOMMENDED MTH HRS LDG	22-Feb-2011 1008.4 855		300			Complete
MOC : COMPLIED WITH										
SB 525A-25-01 R01 25SB-01 : 525A1	B&D CABIN DISPLAY IMPROVEMENT			OPTIONAL MTH			-			
MOC :										
SB 525A-25-04 R01	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION	MKE		OPTIONAL MTH HRS LDG	22-Oct-2011 1208.5 1022		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-25-05 R01 25SB-05 : 525A1	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL MTH HRS LDG	22-Feb-2011 1008.4 855		-			Complete
MOC : COMPLIED WITH										
SB 525A-25-06 25SB-06	AFT CABIN INSULATION MODIFICATION			OPTIONAL MTH			-			
MOC :										
SB 525A-25-07 25SB-07	AIRCELL ANTENA INSTALLATION IMPROVEMENT			OPTIONAL MTH			-			
MOC :										
SB 525A-25-08 25SB-08	PASSENGER SEAT GEAR AND BACKREST LATCH PIN REPLACEMENT			OPTIONAL MTH			-			
MOC :										
SB CIB-25-01	EQUIPMENT/FURNISHINGS - PASSENGER SEAT QUICK RELEASE PIN INSTALLATION			OPTIONAL			-			
MOC :										
SL 525A-25-01 25SL-01	TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	HPN		MANDATORY MTH HRS	17-Sep-2008 946		A/R			Complete
MOC : COMPLIED WITH										
SL 525A-25-02 25SL-02	INSPECTION OF THE BACKREST LATCH PLATES	HPN		MANDATORY MTH HRS	10-Nov-2009 963		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-26-02 26SB-02	FIRE BOTTLE IDENTIFICATION SLEEVE INSTALLATION	HPN		MANDATORY MTH HRS	21-Sep-2005 636		-			Complete
MOC : COMPLIED WITH										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING			MANDATORY MTH			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	MKE	MANDATORY	MTH 19-Jun-2016 HRS 2887.8 LDG 2479 ACH 949.1		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CIL-26-01.									
SB 525A-27-01	R02 STEEP APPROACH CERTIFICATION		OPTIONAL						A/R
MOC :									
SB 525A-27-01	R03 STEEP APPROACH CERTIFICATION		OPTIONAL						-
MOC :									
SB 525A-27-03	R01 FLAP OVERRIDE SWITCH INSTALLATION			MTH 12-Mar-2004					Complete
<i>27SB-03 : 525A1</i>		SWF	RECOMMENDED	HRS 451					
MOC : COMPLIED WITH									
SB 525A-27-04	AILERON CABLE AND FAIRLEAD TUBE REPLACEMENT			MTH 22-Feb-2011					Complete
<i>27SB-04</i>		MKE	RECOMMENDED	HRS 1008.4 LDG 855			A/R		
MOC : COMPLIED WITH									
SB 525A-27-07	ELEVATOR TRIM POINTER IMPROVEMENT			MTH					-
<i>27SB-07</i>			OPTIONAL						
MOC :									
SB 525A-27-08	RUDDER BIAS SIMPLIFICATION		OPTIONAL	MTH					A/R
<i>27SB-08</i>									
MOC :									
SB 525A-27-09	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT			MTH					A/R
<i>27SB-09</i>			OPTIONAL						
MOC :									
SB 525A-27-10	INSPECTION OF TAILCONE WIRE BUNDLE			MTH 17-Sep-2008					Complete
<i>27SB-10</i>		HPN	RECOMMENDED	HRS 946			A/R		
MOC : COMPLIED WITH									
SB 525A-27-13	FLIGHT CONTROLS - VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION			MTH 22-Feb-2011					Complete
		MKE	MANDATORY	HRS 1008.4 LDG 855			A/R		
MOC : COMPLIED WITH									
SL 525A-27-03	RUDDER BIAS PNEUMATIC LINE CLAMP INSPECTION			MTH 22-Apr-2005					Complete
<i>27SL-03</i>		SWF	RECOMMENDED	HRS 586					
MOC : COMPLIED WITH									
SL 525A-27-05	R01 FLAP PUSHROD SAFETY WIRE INSPECTION			MTH 07-Nov-2008					Complete
<i>27SL-05 : 525A1</i>		HPN	RECOMMENDED	HRS 949			A/R		
MOC : COMPLIED WITH									
SL 525A-27-07	FLIGHT CONTROLS - SPEED BRAKE ACTUATOR SCREW REPLACEMENT								-
			OPTIONAL						
MOC :									
SB 525A-28-02	FUEL BOOST PUMP ANNUNCIATION IMPROVEMENT			MTH 12-Mar-2004					Complete
<i>28SB-02</i>		SWF	DISCRETIONARY	HRS 451					
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525A-28-03 28SB-03	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	SWF		IMPROVEMENT MANDATORY	MTH 22-Apr-2005 HRS 586		-			Complete
MOC : COMPLIED WITH										
SB 525A-28-04 28SB-04	FIREWALL SHUTOFF VALVE REPLACEMENT AND FIREWALL SHUTOFF VALVE BRACKET MODIFICATION			OPTIONAL	MTH		A/R			
MOC :										
SL 525A-28-02 28SL-02	FUEL LINE CLEARANCE IMPROVEMENT	HPN		MANDATORY	MTH 18-Mar-2009 HRS 961		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-29-06 R01	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	MKE		MANDATORY	MTH 22-Oct-2011 HRS 1208.5 LDG 1022		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-29-07	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION	KMKE		OPTIONAL	MTH 09-Feb-2019 HRS 4167.1 LDG 3536		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION, SB525A-29-07 DATED MAR. 9, 2011.										
SL 525A-29-03	HYDRAULIC POWER - ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION	KMKE		RECOMMENDED	MTH 22-Jul-2017 HRS 3335.1 LDG 2882 ACH 1124.8		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED SL525A-29-03 DATED JUNE 13, 2017; ENGINE DRIVEN HYDRAULIC PUMP VERIFICATION.										
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES			INFORMATIONAL			-			
MOC :										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
MOC :										
SL 525A-31-01 31SL-01	TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 12 REVISION 2, AFD-3010 ADAPTIVE FLIGHT DISPLAY	SWF		MANDATORY	MTH 21-Sep-2002 HRS 162		-			Complete
MOC : COMPLIED WITH										
SB 525A-32-07 32SB-07	BEARING REPLACEMENT	HPN		MANDATORY	MTH 17-Sep-2008 HRS 946		-			Complete
MOC : COMPLIED WITH										
SB 525A-32-10 R01 32SB-10 : 525A1	MAIN LANDING GEAR ACTUATOR EXTEND HOSE IMPROVEMENT	MKE		RECOMMENDED	MTH 22-Feb-2011 HRS 1008.4 LDG 855		300			Complete
MOC : COMPLIED WITH										
SB 525A-32-11 32SB-11	BRAKE HYDRAULIC AND PNEUMATIC TUBE IMPROVEMENT	SWF		MANDATORY	MTH 25-May-2007 HRS 787		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	KMKE		RECOMMENDED	MTH 16-Mar-2015 HRS 2410.9 LDG 2067		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED CIL-32-03, NLG UPLOCK ROLLER BRACKET INSPECTION, DATED: 11/12/2014.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
MOC :										
SL 525A-32-03 32SL-03	HYDRAULIC TUBE INSPECTION	ICT		RECOMMENDED	MTH 02-May-2002 HRS 12		-			Complete
MOC : COMPLIED WITH										
SL 525A-32-07 32SL-07	BRAKE SUPPLY LINE FILTER INSPECTION	SWF		RECOMMENDED	MTH 25-May-2007 HRS 787		A/R			Complete
MOC : COMPLIED WITH										
SL 525A-32-08 R01 32SL-08 : 525A1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SL 525A-32-12 32SL-12	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	MKE		RECOMMENDED	MTH 22-Feb-2011 HRS 1008.4 LDG 855		150			Complete
MOC : COMPLIED WITH										
SL 525A-32-13 R01 32SL-13 : 525A1	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION	MKE		RECOMMENDED	MTH 22-Oct-2011 HRS 1208.5 LDG 1022		300			Complete
MOC : COMPLIED WITH										
SL 525A-32-14 R01 32SL-14 : 525A1	AUXILIARY BRAKE TUBE INSPECTION	MKE		RECOMMENDED	MTH 13-Apr-2014 HRS 1973.7 LDG 1704		300			Complete
SERVICE BULLETIN ON HOLD.										
MOC : COMPLIED WITH - ACCOMPLISHED SL525A-32-14 REVISION 1, DATED OCTOBER 31, 2008; AUXILIARY BRAKE TUBE INSPECTION.										
SL 525A-32-17 32SL-17	EMERGENCY GEAR RELEASE INSPECTION	HPN		MANDATORY	MTH 01-Jun-2010 HRS 994 LDG 837		A/R			Complete
MOC : COMPLIED WITH										
SL 525A-32-18	LANDING GEAR- TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1651-32-2, LANDING GEAR- BRAKE ASSEMBLY- REPLACEMENT OF BLEEDER SCREWS AND BLEEDER FITTINGS WITH BLEEDER PLUGS	MKE		MANDATORY	MTH 18-Jan-2012 HRS 1308.7 LDG 1095		-			Complete
MOC : COMPLIED WITH										
SB 525A-33-02 33SB-02	WING TIP ANTICOLLISION LIGHT MODIFICATION	SWF		RECOMMENDED	MTH 22-Apr-2005 HRS 586		-			Complete
MOC : COMPLIED WITH										
SB 525A-33-03 33SB-03	CHART LIGHT MODIFICATION	KMKE		OPTIONAL	MTH 19-Jan-2013 HRS 1554.9 LDG 1327		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl	Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL						
MOC :										
SB 525A-34-01 <i>34SB-01</i>	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION	*CF	OPTIONAL		MTH 02-May-2002					Complete
MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH AT FACTORY OR IS A FACTORY OPTION.										
SB 525A-34-04 <i>34SB-04</i>	FLIGHT GUIDANCE COMPUTER VOR IMPROVEMENT	SWF	RECOMMENDED		MTH 22-Apr-2005 HRS 586					Complete
MOC : COMPLIED WITH										
SB 525A-34-09 <i>34SB-09</i>	ATTITUDE INDICATOR AND HORIZONTAL SITUATION INDICATOR MODIFICATION	HPN	RECOMMENDED		MTH 23-Dec-2004 HRS 549					N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 525A-34-11 R01 <i>34SB-11 : 525R1</i>	RADIO ALTIMETER CONVERTER UPGRADE			DISCRETIONARY	MTH		A/R			
MOC :										
SB 525A-34-14 <i>34SB-14</i>	GARMIN GNS-530A RADIOS/FMS & GTX-330D TRANSPONDER INSTALLATION		OPTIONAL		MTH					
MOC :										
SB 525A-34-15 <i>34SB-15</i>	MST-67A DIVERSITY TRANSPONDER INSTALLATION		OPTIONAL		MTH					
MOC :										
SB 525A-34-16 <i>34SB-16</i>	GARMIN GTX-330D TRANSPONDER INSTALLATION UPGRADE		OPTIONAL		MTH		A/R			
MOC :										
SB 525A-34-17 R02 <i>34SB-17 : 525R2</i>	GARMIN GTX-330(D) TRANSPONDER SOFTWARE UPGRADE TO 4.01		OPTIONAL				A/R			
MOC :										
SB 525A-34-19 R01 <i>34SB-19 : 525A1</i>	TERRAIN AWARENESS WARNING SYSTEM (TAWS) UPGRADE TO SOFTWARE LEVEL 1.13	MKE	OPTIONAL		MTH 31-Jul-2012 HRS 1434.2 LDG 1209		A/R			N/A
MOC : NOT APPLICABLE - DUE TO EQUIPMENT INSTALLED										
SB 525A-34-20 R02 <i>34SB-20 : 525A2</i>	FILE SERVER INSTALLATION AND MULTIFUNCTION DISPLAY (MFD) UPDATE FOR CHARTS AND XM SATELLITE WEATHER		OPTIONAL		MTH		A/R			
MOC :										
SB 525A-34-40	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE		OPTIONAL							
MOC :										
SB CIB-34-04	ROCKWELL COLLINS ADAPTIVE FLIGHT DISPLAY UPGRADE		OPTIONAL							
MOC :										
SL CIL-35-01	TRANSMITTAL OF BE AEROSPACE SERVICE BULLETIN 118077-35-01	KMKE	MANDATORY		MTH 15-Dec-2013 HRS 1864.1 LDG 1603					N/A
MOC : NOT APPLICABLE - CIL-35-01 IS NOT APPLICABLE. EROS BRAND SMOKE GOGGLES CURRENTLY INSTALLED.										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KMKE	MANDATORY	MTH 31-Jan-2016 DAYS 2731.2 HRS 2344 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH CIL-35-05, TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001 DATED 01/08/2016 ON CREW MASKS P/N MC10-16-101, S/N 121031 AND P/N MC10-16-101,S/N 100250 AND FOUND NOT APPLICABLE BY P/N. NO FURTHER ACTION REQUIRED.									
SL 525A-35-02 R01	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	MKE	MANDATORY	MTH 31-Jul-2012 HRS 1434.2 LDG 1209		-			Complete
MOC : COMPLIED WITH									
SL 525A-35-02 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	MKE	MANDATORY	MTH 07-Dec-2012 HRS 1520.7 LDG 1295		-			Complete
MOC : COMPLIED WITH - SL525A-35-02 R1 WAS PREVIOUSLY COMPLETED IN MKE ON JULY 31, 2012									
SB 525A-36-04	PNEUMATIC - MOISTURE TRAP INSTALLATION		OPTIONAL			A/R			
MOC :									
SB 525A-52-03 R01	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION		OPTIONAL			A/R			
<i>52SB-03 : 525R1</i>									
MOC :									
ASL 525A-52-01	EMERGENCY DOOR INSPECTION	HPN	MANDATORY	MTH 17-Sep-2008 HRS 946		A/R			Complete
<i>52SLA01</i>									
MOC : COMPLIED WITH									
SL CIL-52-01	DOORS - EMERGENCY DOOR INSPECTION	MKE	MANDATORY	MTH 26-May-2013 HRS 1636.2 LDG 1391		-			Complete
MOC : COMPLIED WITH - ACCOMPLISHED CIL-52-01 DATED NOVEMBER 27, 2012; EMERGENCY DOOR INSPECTION.									
SB 525A-53-01 R01	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S)	SWF	MANDATORY	MTH 31-Oct-2008 HRS 947		A/R			Complete
<i>53SB-01 : 525A1</i>									
MOC : COMPLIED WITH - FOUND PREVIOUSLY COMPLIED WITH.									
ASL 525A-53-04	RELIEF TUBE CORROSION	SWF	MANDATORY	MTH 25-May-2007 HRS 787		A/R			Complete
<i>53SLA04</i>									
MOC : COMPLIED WITH									
ASL 525A-53-05	RELIEF TUBE CORROSION INSPECTION	SWF	MANDATORY	MTH 31-Oct-2008 HRS 947		A/R			Complete
<i>R05 53SLA05 : 525A5</i>									
MOC : COMPLIED WITH - FOUND PREVIOUSLY COMPLIED WITH.									
SL 525A-53-09	INTERCOSTAL DRAINAGE PATH INSPECTION	MKE	RECOMMENDED	MTH 22-Feb-2011 HRS 1008.4 LDG 855		A/R			Complete
<i>53SL-09</i>									
MOC : COMPLIED WITH									
SL 525A-53-10	UPPER TAILCONE SKIN INSPECTION	HPN	MANDATORY	MTH 06-Jul-2010 HRS 994 LDG 837		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525A-54-01 R01	FIREWALL BOX			RECOMMENDED			A/R			
MOC :										
SB 525A-54-01 <i>54SB-01</i>	FIREWALL BOX REPAIR	SWF		RECOMMENDED	MTH 25-May-2007 HRS 787		-			Complete
MOC : COMPLIED WITH										
SB 525A-57-01 <i>57SB-01</i>	CENTER WING NOISE REDUCTION IMPROVEMENT	MKE		DISCRETIONARY	MTH 22-Feb-2011 HRS 1008.4 LDG 855		-			Complete
MOC : COMPLIED WITH										
SL 525A-57-01 <i>57SL-01</i>	ACCESS DOOR DRAINAGE IMPROVEMENT	SWF		RECOMMENDED	MTH 09-Mar-2006 HRS 654		-			Complete
MOC : COMPLIED WITH										
SB 525A-71-02 R01 <i>71SB-02 : 525A1</i>	UPPER ENGINE COWL SUPPORT MODIFICATION			OPTIONAL	MTH		-			
MOC :										
SL 525A-71-03 R02	POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT	KMKE		MANDATORY	MTH 07-Sep-2016 HRS 2980.9 LDG 2564		-			N/A
MOC : NOT APPLICABLE - SL525A-71-03 R3 POWERPLANT - FUEL AND HYDRAULIC HOSE REPLACEMENT. THIS SL IS NOT APPLICABLE DUE TO SERIAL NUMBER RANGE.										
SL WI-71-1064-CN E1	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-71-1064-CN E2	CANCELED - POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL			CANCELLED			-			
MOC :										
SL WI-71-1064 E1	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
MOC :										
SL WI-71-1064 E2	POWER PLANT - WATER RINSE PROCEDURE - REVISION TO MAINTENANCE MANUAL						-			
MOC :										
SB FJ44-05-002 R02 E1	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-05-002 R02 E2	UNSERVICEABLE PARTS - NOTIFICATION			INFORMATIONAL			-			
MOC :										
SB FJ44-72-051 R03 E1	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)	MKE		RECOMMENDED	MTH 03-Apr-2014 HRS 1973.7 LDG 1704		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-051 R03 E2	REWORK NAMEPLATE (SUPERSEDED BY FJ44-72-051 R04)	KMKE		RECOMMENDED	MTH 27-Aug-2014 HRS 2151.8 LDG 1855		-			Complete
MOC : COMPLIED WITH - INSPECTED NAME PLATE & FOUND TO HAVE BEEN PREVIOUSLY COMPLIED WITH. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-051 R04 E1	REWORK NAMEPLATE			RECOMMENDED			-			
MOC :										
SB FJ44-72-051 R04 E2	REWORK NAMEPLATE			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R04 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R04 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R05)			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R05 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R05 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER (SUPERSEDED BY FJ44-72-054 R06)			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R06 E1	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
MOC :										
SB FJ44-72-054 R06 E2	GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
MOC :										
SB FJ44-72-077 R02 E1	ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R02 E2	ENGINE - IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R03)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R03 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R03 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK (SUPERSEDED BY FJ44-72-077 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-077 R04 E1	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK			OPTIONAL	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-077 R04 E2	IP COMPRESSOR STATOR (STAGE 1-2) - REWORK			OPTIONAL	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-079 R02 E1	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
MOC :										
SB FJ44-72-079 R02 E2	CANCELLED - ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			CANCELLED			-			
MOC :										
SB FJ44-72-085 R05 E1	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED	HRS		DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-085 R05 E2	ENGINE - IP BLEED VALVE - REPLACE (SUPERSEDED BY FJ44-72-085 R06)			RECOMMENDED	HRS		DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-085 R06 E1	IP BLEED VALVE - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-085 R06 E2	IP BLEED VALVE - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-104 R01 E1	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R02)			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R01 E2	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R02)			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R02 E1	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R03)	KMKE		OPTIONAL	MTH 31-Mar-2016 HRS 2828.7 LDG 2433		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO.1 ENGINE, WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-72-104, REVISION 2, UPGRADE GEARBOX (4K MAG SEAL TO SPRING LOADED CONFIGURATION), DATED:24 MAR 2015.										
SB FJ44-72-104 R02 E2	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R03)	KMKE		OPTIONAL	MTH 31-Mar-2016 HRS 2828.7 LDG 2433		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH NO.2, ENGINE WILLIAMS INTERNATIONAL SERVICE BULLETIN FJ44-72-104, REVISION 2, UPGRADE GEARBOX (4K MAG SEAL TO SPRING LOADED CONFIGURATION), DATED:24 MAR 2015.										
SB FJ44-72-104 R04 E1	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
MOC :										
SB FJ44-72-104 R04 E2	UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
MOC :										
SB FJ44-72-104 E1	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R01)			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-104 E2	ENGINE - UPGRADE GEARBOX (4K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-104 R01)			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R03 E1	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-105 R03 E2	UPGRADE GEARBOX (4K SPRING LOADED) TO IMPROVED CONFIGURATION (SUPERSEDED BY FJ44-72-105 R04)			OPTIONAL			-			
MOC :										
SB FJ44-72-108 R01 E1	ACCESSORY DRIVE SHAFT - REPLACE			RECOMMENDED	MTH HRS			DUE DUE DUE	4473.7	295.4
MOC :										
SB FJ44-72-108 R01 E2	ACCESSORY DRIVE SHAFT - REPLACE			RECOMMENDED	MTH HRS			DUE DUE DUE	4473.7	295.4
MOC :										
SB FJ44-72-108 E1	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-108 E2	ACCESSORY DRIVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-108 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-109 E1	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS			DUE DUE	4473.7	295.4
MOC :										
SB FJ44-72-109 E2	ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE			RECOMMENDED	HRS			DUE DUE	4473.7	295.4
MOC :										
SB FJ44-72-111 R02 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-111 R02 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION	MKE		RECOMMENDED	MTH 03-Apr-2014 HRS 1973.7 LDG 1704		-			Complete
MOC : COMPLIED WITH										
SB FJ44-72-111 E1	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-111 E2	ENGINE - 1ST LP TURBINE NOZZLE - INSPECTION (SUPERSEDED BY FJ44-72-111 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-119 E1	HP COMPRESSOR ROTOR - REWORK			RECOMMENDED	MTH HRS			DUE DUE DUE	4473.7	295.4
MOC :										
SB FJ44-72-119 E2	HP COMPRESSOR ROTOR - REWORK			RECOMMENDED	MTH HRS			DUE DUE DUE	4473.7	295.4
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-123 R01 E1	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-123 R01 E2	CANCELLED - INNER GUIDED ROLLER BEARING (NO. 3 BEARING) - REPLACE			CANCELLED			-			
MOC :										
SB FJ44-72-130 R01 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R01 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R02 E1	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 R02 E2	HP COMPRESSOR ROTOR - INSPECTION			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 E1	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-130 E2	HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R01)			RECOMMENDED			-			
MOC :										
SB FJ44-72-134 E1	1ST LP TURBINE NOZZLE HEATSHIELD HOUSING ASSEMBLY - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-140 E1	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY	HRS		DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-140 E2	GEARBOX HOUSING ASSEMBLY - INSPECTION			MANDATORY	HRS		DUE DUE		4473.7	295.4
MOC :										
SB FJ44-72-142 R01 E1	NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	New Req
MOC :										
SB FJ44-72-142 R01 E2	NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	New Req
MOC :										
SB FJ44-72-142 E1	NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE			RECOMMENDED			-			
MOC :										
SB FJ44-72-142 E2	NO. 1 CARBON SEAL ASSEMBLY & SEAL RUNNER - REPLACE			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-143 E1	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-143 E2	BLEED VALVE SHAFT - REPLACE (SUPERSEDED BY FJ44-72-143 R01)			RECOMMENDED			-			
	MOC :									
SB FJ44-72-149 E1	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-72-149 E2	SEAL & BEARING RETAINER HOUSING AND LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-73-018 R03 E1	REPLACE INTEGRATED FUEL CONTROL UNIT (SUPERSEDED BY FJ44-73-018 R04)	KMKE		RECOMMENDED	MTH 13-Sep-2018 HRS 3985.7 LDG 3391		-			Complete
	MOC :									
SB FJ44-73-018 R03 E2	REPLACE INTEGRATED FUEL CONTROL UNIT (SUPERSEDED BY FJ44-73-018 R04)			RECOMMENDED			-			
	MOC :									
SB FJ44-73-018 R04 E1	INTEGRATED FUEL CONTROL UNIT - REPLACE (SUPERSEDED BY FJ44-73-018 R05)	KMKE		RECOMMENDED	MTH 13-Sep-2018 HRS 3985.7 LDG 3391		-			Complete
	MOC :									
	MOC :									
SB FJ44-73-018 R04 E2	INTEGRATED FUEL CONTROL UNIT - REPLACE (SUPERSEDED BY FJ44-73-018 R05)			RECOMMENDED			-			
	MOC :									
SB FJ44-73-018 R05 E1	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT - REPLACE	KMKE		RECOMMENDED	MTH 13-Sep-2018 HRS 3985.7 LDG 3391		-			Complete
	MOC :									
	MOC :									
SB FJ44-73-018 R05 E2	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT - REPLACE			RECOMMENDED			-			
	MOC :									
SB FJ44-73-130 R01 E1	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT (SUPERSEDED BY SL680 -05-02 R02)	KMKE			MTH 21-Jul-2017 HRS 3335.1 LDG 2882		-			Complete
	MOC :									
	MOC :									
SB FJ44-73-130 R01 E2	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT (SUPERSEDED BY SL680 -05-02 R02)	KMKE			MTH 22-Jul-2017 HRS 3335.1 LDG 2882		-			Complete
	MOC :									
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-73-130 R02 E1	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT (SUPERSEDED BY FJ44-73-130 R03)								
	MOC :								
SB FJ44-73-130 R02 E2	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT (SUPERSEDED BY FJ44-73-130 R03)								
	MOC :								
SB FJ44-73-130 R03 E1	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT		MANDATORY						
	MOC :								
SB FJ44-73-130 R03 E2	ENGINE FUEL AND CONTROL - INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT		MANDATORY						
	MOC :								
SB FJ44-73-130 E1	INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT (SUPERSEDED BY FJ44-73-130 R01)								
	MOC :								
SB FJ44-73-130 E2	INTEGRATED FUEL CONTROL UNIT (IFCU) - ACCELERATION & THROTTLE CHECK ADJUSTMENT (SUPERSEDED BY FJ44-73-130 R01)								
	MOC :								
SB WI-73-1004 R02 -CN E1	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		CANCELLED						
	MOC :								
SB WI-73-1004 R02 -CN E2	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		CANCELLED						
	MOC :								
SB WI-73-1011-CN E1	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		CANCELLED						
	MOC :								
SB WI-73-1011-CN E2	CANCELLED - ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		CANCELLED						
	MOC :								
SB WI-73-1011 E1	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		RECOMMENDED						
	MOC :								
SB WI-73-1011 E2	ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE		RECOMMENDED						
	MOC :								
SB WI-73-1012 E1	ENGINE FUEL AND CONTROL - FCU/FUEL HEATER FUEL TUBE ASSEMBLIES - REPLACE		RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	New Req
	MOC :								
SB WI-73-1012 E2	ENGINE FUEL AND CONTROL - FCU/FUEL HEATER FUEL TUBE ASSEMBLIES - REPLACE		RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	New Req
	MOC :								
SB WI-75-1000 E1	AIR - LOOP CLAMP - INSTALL		RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	295.4
	MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB WI-75-1000 E2	AIR - LOOP CLAMP - INSTALL			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB WI-75-1002 E1	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB WI-75-1002 E2	AIR - I.P. BLEED VALVE LEVER PIN - REPLACE			RECOMMENDED	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB 525A-78-02 R01	THRUST ATTENUATOR PADDLE IMPROVEMENT			MANDATORY	MTH 28-Apr-2010 HRS 991 LDG 835		-			N/A
MOC : NOT APPLICABLE - ORIGINAL ISSUE HAS ALREADY BEEN COMPLIED WITH										
ASL 525A-78-01 78SLA01	THRUST ATTENUATOR PADDLE INSPECTION			MANDATORY	MTH 10-Nov-2009 HRS 963		A/R			Complete
MOC : COMPLIED WITH										
SB 525A-79-02 79SB-02	ENGINE GEARBOX BREATHER LINE INSTALLATION			DISCRETIONARY	MTH		-			
MOC : - SERVICE BULLETIN ON HOLD.										
SB FJ44-79-007 R04 E1	ENGINE - LUBE PUMP - REWORK TO P/N 110487			RECOMMENDED			-			
MOC :										
SB FJ44-79-007 R04 E2	ENGINE - LUBE PUMP - REWORK TO P/N 110487			RECOMMENDED			-			
MOC :										
SB FJ44-79-011 R01 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)			MANDATORY			-			
MOC :										
SB FJ44-79-011 R01 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R02)			MANDATORY			-			
MOC :										
SB FJ44-79-011 R03 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)			MANDATORY			-			
MOC :										
SB FJ44-79-011 R03 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R04)			MANDATORY			-			
MOC :										
SB FJ44-79-011 R04 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										
SB FJ44-79-011 R04 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE			MANDATORY	MTH HRS		DUE DUE DUE		4473.7	295.4
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-79-011 E1	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
	MOC :									
SB FJ44-79-011 E2	MAGNETIC SELF-CLOSING VALVE - REPLACE (SUPERSEDED BY FJ44-79-011 R01)			MANDATORY			-			
	MOC :									
SB FJ44-79-015 E1	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
	MOC :									
SB FJ44-79-015 E2	CANCELLED - OIL - LUBE AND SCAVENGE PUMP ASSEMBLY - TIME EXTENSION OF TIME BETWEEN OVERHAUL (TBO) FOR TOTAL ASSURANCE PROGRAM (TAP)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1998-25-02 <i>34AD-02 : 525</i>	BFGOODRICH SKYWATCH SKY497	ICT		MANDATORY	MTH 02-May-2002 HRS 12		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 1999-08-21 <i>35AD-01 : 525</i>	APPLIANCE AD - PURITAN-BENNETT AERO SYSTEMS CO.	ICT		MANDATORY	MTH 02-May-2002 HRS 12		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
FAA 2001-23-17 <i>34AD-03</i>	APPLIANCE AD - GARMIN GNS 430	ICT		MANDATORY	MTH 02-May-2002 HRS 12		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2002-20-09 <i>31AD-01</i>	APPLIANCE AD - COLLINS AFD-3010 AFD UNITS	SWF		MANDATORY	MTH 13-Jun-2003 HRS 293		A/R			Complete
MOC : COMPLIED WITH										
FAA 2003-13-08 <i>34AD-01</i>	APPLIANCE AD - TAWS 8000 TERRAIN AWARENESS	SWF		MANDATORY	MTH 12-Mar-2004 HRS 451		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
FAA 2004-08-15 <i>34AD-02</i>	TAWS 8000 TERRAIN AWARENESS	HPN		MANDATORY	MTH 23-Dec-2004 HRS 549		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2									
MOC : MANDATORY -										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK									
MOC : MANDATORY -										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS									
MOC : MANDATORY -										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT									
MOC : MANDATORY MTH -										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS									
MOC : KMKE MTH 11-Oct-2017 HRS 3437.9 LDG 2973 - N/A										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT									
MOC : KMKE MTH 11-Oct-2017 HRS 3437.9 LDG 2973 - N/A										
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD2017-16-01 PARAGRAPH J. AMERI-KING CORPORATION MODEL AK-450 OR 451 NOT INSTALLED ON THIS AIRCRAFT.										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KMKE	MANDATORY	MTH 11-Oct-2017 HRS 3437.9 LDG 2973		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD2017-16-01 AMERI-KING CORPORATION MODEL AK-450 OR 451 NOT INSTALLED ON THIS AIRCRAFT.									
FAA 2005-17-11 26AD-02	PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES	HPN	MANDATORY	MTH 21-Sep-2005 HRS 636		-			Complete
MOC : COMPLIED WITH									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	KMKE	MANDATORY	MTH 07-Sep-2016 HRS 2980.9 LDG 2564		-			N/A
MOC : NOT APPLICABLE - FAA AD2014-18-01 NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS IS NOT APPLICABLE DUE TO UNIT NOT BEING INSTALLED ON AIRCRAFT.									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	KMKE	MANDATORY	MTH 31-May-2015 HRS 2485.7 LDG 2129		-			N/A
MOC : NOT APPLICABLE - AD 2015-10-51-E , AVIDYNE INTEGRATED FLIGHT DISPLAY DOES NOT APPLY TO THIS AIRCRAFT AS EQUIPMENT IS NOT INSTALLED. NO ACTION IS REQUIRED.									
FAA 2015-10-51	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS		MANDATORY			-			
MOC :									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KMKE	MANDATORY	MTH 31-May-2015 HRS 2485.7 LDG 2129		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOTS & CO-PILOTS OXYGEN MASKS. PILOTS MASK IS P/N MC-16-101, S/N 121031 - DMF 2/2007 & LAST OVERHAULED 8/2014. CO-PILOTS MASK IS P/N MC10-16-101, S/N 100250 - DMF3/2002 & LAST OVERHAULED 9/2014. THESE MASKS ARE NOT AFFECTED BY AD 2015-08-07 IN ACCORDANCE WITH THE ZODIAC SB MXH-35-240 R7 . NO ACTION IS REQUIRED.									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KMKE	MANDATORY	MTH 31-May-2015 HRS 2485.7 LDG 2129		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOTS & CO-PILOTS OXYGEN MASKS. PILOTS MASK IS P/N MC-16-101, S/N 121031 - DMF 2/2007 & LAST OVERHAULED 8/2014. CO-PILOTS MASK IS P/N MC10-16-101, S/N 100250 - DMF3/2002 & LAST OVERHAULED 9/2014. THESE MASKS ARE NOT AFFECTED BY AD 2015-08-07 IN ACCORDANCE WITH THE ZODIAC SB MXH-35-240 R7 . NO ACTION IS REQUIRED.									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KMKE	MANDATORY	MTH 31-May-2015 HRS 2485.7 LDG 2129		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOTS & CO-PILOTS OXYGEN MASKS. PILOTS MASK IS P/N MC-16-101, S/N 121031 - DMF 2/2007 & LAST OVERHAULED 8/2014. CO-PILOTS MASK IS P/N MC10-16-101, S/N 100250 - DMF3/2002 & LAST OVERHAULED 9/2014. THESE MASKS ARE NOT AFFECTED BY AD 2015-08-07 IN ACCORDANCE WITH THE ZODIAC SB MXH-35-240 R7 . NO ACTION IS REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KMKE	MANDATORY	MTH 31-Jan-2016 DAYS 2731.2 HRS 2344 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 (PAR G) INSPECTION ON CREW MASKS P/N MC10-16-101, S/N 121031 AND P/N MC10-16-101, S/N 100250 AND FOUND NOT APPLICABLE BY P/N. NO FURTHER ACTIONREQUIRED.									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KMKE	MANDATORY	MTH 31-Jan-2016 DAYS 2731.2 HRS 2344 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 (PAR G) INSPECTION ON CREW MASKS P/N MC10-16-101, S/N 121031 AND P/N MC10-16-101, S/N 100250 AND FOUND NOT APPLICABLE BY P/N. NO FURTHER ACTIONREQUIRED.									
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KMKE	MANDATORY	MTH 31-Jan-2016 DAYS 2731.2 HRS 2344 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 (PAR G) INSPECTION ON CREW MASKS P/N MC10-16-101, S/N 121031 AND P/N MC10-16-101, S/N 100250 AND FOUND NOT APPLICABLE BY P/N. NO FURTHER ACTIONREQUIRED.									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KMKE	MANDATORY	MTH 31-Jan-2016 DAYS 2731.2 HRS 2344 LDG		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 (PAR G) INSPECTION ON CREW MASKS P/N MC10-16-101, S/N 121031 AND P/N MC10-16-101, S/N 100250 AND FOUND NOT APPLICABLE BY P/N. NO FURTHER ACTIONREQUIRED.									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KMKE	MANDATORY	MTH 31-Jan-2016 HRS 2731.2 LDG 2344		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 (PAR G) INSPECTION ON CREW MASKS P/N MC10-16-101, S/N 121031 AND P/N MC10-16-101, S/N 100250 AND FOUND NOT APPLICABLE BY P/N. NO FURTHER ACTIONREQUIRED.									
FAA 2015-23-09	APLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KMKE	MANDATORY	MTH 31-Jan-2016 HRS 2731.2 LDG 2344		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2015-23-09 (PAR G) INSPECTION ON CREW MASKS P/N MC10-16-101, S/N 121031 AND P/N MC10-16-101, S/N 100250 AND FOUND NOT APPLICABLE BY P/N. NO FURTHER ACTIONREQUIRED.									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KMKE	MANDATORY	MTH 07-Sep-2016 HRS 2980.9 LDG 2564		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT IS NOT APPLICABLE PBE IS NOT INSTALLED ON AIRCRAFT.									



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KMKE		MANDATORY	MTH 07-Sep-2016 HRS 2980.9 LDG 2564		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT IS NOT APPLICABLE PBE IS NOT INSTALLED ON AIRCRAFT.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KMKE		MANDATORY	MTH 07-Sep-2016 HRS 2980.9 LDG 2564		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT IS NOT APPLICABLE PBE IS NOT INSTALLED ON AIRCRAFT.										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KMKE		MANDATORY	MTH 07-Sep-2016 HRS 2980.9 LDG 2564		-			N/A
MOC : NOT APPLICABLE - FAA AD2016-11-20 OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT IS NOT APPLICABLE PBE IS NOT INSTALLED ON AIRCRAFT.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KMKE		MANDATORY	MTH 11-Oct-2017 HRS 3437.9 LDG 2973		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD2017-18-12 PARAGRAPH G. B/E AEROSPACE PBE P/N 119003-11 NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KMKE		MANDATORY	MTH 11-Oct-2017 HRS 3437.9 LDG 2973		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD2017-18-12 PARAGRAPH H. B/E AEROSPACE PBE P/N 119003-11 NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KMKE		MANDATORY	MTH 11-Oct-2017 HRS 3437.9 LDG 2973		-			N/A
MOC : NOT APPLICABLE										
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KMKE		MANDATORY	MTH 11-Oct-2017 HRS 3437.9 LDG 2973		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH FAA AD2017-18-12 PARAGRAPH I AND J. B/E AEROSPACE PBE P/N 119003-11 NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2008-03-10 53AD-01	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	SWF		AIRWORTHINESS	MTH 03-Nov-2008 HRS 947		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
FAA 2010-12-01	DETECT AND CORRECT LOOSE AND DAMAGED FASTENERS, AND CRACKS IN THRUST ATTENUATOR PADDLES	MKE	MANDATORY		MTH 22-Feb-2011		A/R			Complete
					HRS 1008.4					
					LDG 855					

MOC : COMPLIED WITH



CESCOM 10 - Aircraft Status Report

Owner: **CITATION PARTNERS, LLC**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0071**
 Unit: **0071** Reg No: **N701SF**
 Airworthiness: **02-May-2002**
 Print Date: **27-Feb-2019 11:37AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4178.3	3546	21-Feb-2019	1.18
ENG 1	4178.3	3546	21-Feb-2019	1.18
ENG 2	4188.5	3552	21-Feb-2019	1.18
AIR COND	1268		21-Feb-2019	.12

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
23FO166	CHIME-CABIN FACTORY OPTION			166 FO	MTH 02-May-2002		-			
<i>23FO631X</i> <i>23FO631 : X</i>	HF COMM-PROVISIONS KHF-950 FACTORY OPTION			631X FO	MTH 02-May-2002		-			
<i>23FO634L</i> <i>23FO634 : L</i>	RECORDER-CKPT VOICE PROVISIONS FACTORY OPTION			634L FO	MTH 02-May-2002		-			
<i>23FO674B</i> <i>23FO674 : B</i>	SPEAKER-COCKPIT MUTE FACTORY OPTION			674B FO	MTH 02-May-2002		-			
<i>24FO186K</i> <i>24FO186 : K</i>	BATTERY-44A HOUR FACTORY OPTION			186K FO	MTH 02-May-2002		-			
<i>25FO130C</i> <i>25FO130 : C</i>	TOLIET FLUSHING-RH NONBELTED FACTORY OPTION			130C FO	MTH 02-May-2002		-			
<i>25FO175B</i> <i>25FO175 : B</i>	LOCATOR BEACON-ARTEX FACTORY OPTION			175B FO	MTH 02-May-2002		-			
<i>25FO50G</i> <i>25FO50 : G</i>	LIGHTING-INDIRECT FACTORY OPTION			50G FO	MTH 02-May-2002		-			
<i>25FO720B</i>	VINYL COVERED OVERHEAD FACTORY OPTION			720B FO	MTH 02-May-2002		-			
<i>25FO728A</i>	ALLOY COLORED CKP & CB DOOR TR FACTORY OPTION			728A FO	MTH 02-May-2002		-			
<i>33FO056B</i> <i>33FO056 : B</i>	LIGHTS-PULSE FACTORY OPTION			56B FO	MTH 02-May-2002		-			
<i>34FO011A</i> <i>34FO011 : A</i>	INDEXER-AOA FACTORY OPTION			11A FO	MTH 02-May-2002		-			
<i>34FO607F</i> <i>34FO607 : F</i>	THIRD DISPLAY-COLLINS (EXCHNG) FACTORY OPTION			607F FO	MTH 02-May-2002		-			
<i>34FO635M</i> <i>34FO635 : M</i>	TCAS 1- HONEYWELL FACTORY OPTION			635M FO	MTH 02-May-2002		-			
<i>34FO691B</i> <i>34FO691 : B</i>	EGPWS-AMERICAN DATA BASE FACTORY OPTION			691B FO	MTH 02-May-2002		-			
<i>34FO801</i>	KIT FOR BF GOODRICH, WX-1000E EFIS STORMSCOPE FACTORY OPTION			801 FO	MTH 02-May-2002		-			
<i>35FO066F</i> <i>35FO066 : F</i>	OXYGEN-50CU FT BOTTLE FACTORY OPTION			66F FO	MTH 02-May-2002		-			
<i>38FO102</i>	RELIEF TUBE-CREW SEAT FACTORY OPTION			102 FO	MTH 02-May-2002		-			